| Heritage Asset Survey | | | | | | |
|--|-----------------|---|---|---------------------------------|--|--|
| Building Name: | | | Building Reference Number: | | | |
| Former Stables And Outbuildings | | | LL5016 | | | |
| Building Address: | | | Listing Grade: | | | |
| Cavendish Mews | | | | | | |
| Aldershot | | | 1 11 | | | |
| Hampshire | | | | | | |
| | | | II* | | | |
| Listing Criteria Met (see Box B of the | B, G | | II* Locally Listed + | | | |
| SPD) | | | | | | |
| , | 26th March 2012 | | Conservation Area: Yes: No: + | | | |
| Former stables, | now garages | , c1 | 880 and c1910. Red brick in | | | |
| | | | n two sections; a 'U' plan | | | |
| | | | two-storey coach house range | | | |
| and associated | buildings to | the | east. Casement windows, some | | | |
| replacement. Ve | nted louvres | to | ridge. Late 20 th century garaq | ge | | |
| doors inserted | to some stab: | le s | ections. Remnant survival of | | | |
| square block pa | vers in place | es. | | | | |
| | | | | | | |
| | | | | | | |
| Condition Survey: 1 - 5 | | | | | | |
| Condition Survey: 1 - 5 |) | | | | | |
| | | | | | | |
| | Poor 3 | Fair | 4 Good 5 Excellent | | | |
| 1 Very Bad | | | | 4 | | |
| | | Fair 3 | 4 Good 5 Excellent Walls | 4 | | |
| 1 Very Bad | | 3 | Walls | | | |
| 1 Very Bad 2 | | | | 4 | | |
| 1 Very Bad 2 | | 3 | Walls | | | |
| 1 Very Bad Roof Weather Penetration | | 3 | Walls Stability | 4 | | |
| 1 Very Bad Roof Weather Penetration | | 3 | Walls Stability | 4 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag | | 3 3 4 | Walls Stability Plumb Local Building Cracking | 4 4 3 | | |
| 1 Very Bad Roof Weather Penetration Spread | | 3 3 4 | Walls Stability Plumb | 4 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering | | 3 3 4 4 3 | Walls Stability Plumb Local Building Cracking Pointing | 4 3 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag | | 3 3 4 | Walls Stability Plumb Local Building Cracking | 4 4 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments | Poor 3 | 3 3 4 4 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread | 4 4 3 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering | Poor 3 | 3 3 4 4 3 | Walls Stability Plumb Local Building Cracking Pointing | 4 3 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Val | Poor 3 | 3 3 4 4 3 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling | 4 4 3 3 4 4 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments | Poor 3 | 3 3 4 4 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread | 4 4 3 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Val Flashing | Poor 3 | 3 3 4 4 3 3 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling EV. Rising Damp | 4 4 3 3 4 4 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Val | Poor 3 | 3 3 4 4 3 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling | 4 4 3 3 4 4 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Val Flashing Rain Water Goods | Poor 3 | 3 3 4 4 3 3 3 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling EV. Rising Damp Settlement | 4 4 3 4 4 3 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Val Flashing | Poor 3 | 3 3 4 4 3 3 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling EV. Rising Damp | 4 4 3 3 4 4 3 | | |
| Toof Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Value) Flashing Rain Water Goods Chimneys | Poor 3 | 3 3 4 4 3 3 3 3 n/a | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling EV. Rising Damp Settlement Lintels | 4 4 3 4 4 4 | | |
| 1 Very Bad Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Val Flashing Rain Water Goods | Poor 3 | 3 3 4 4 3 3 3 3 | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling EV. Rising Damp Settlement | 4 4 3 4 4 3 | | |
| Toof Roof Weather Penetration Spread Sag Covering Abutments Weathering Detail (Value) Flashing Rain Water Goods Chimneys | Poor 3 | 3 3 4 4 3 3 3 3 n/a | Walls Stability Plumb Local Building Cracking Pointing Roofspread Spalling EV. Rising Damp Settlement Lintels | 4 4 3 4 4 4 | | |

| Front Principal Windows | 2/3 | Post Joints | n/a |
|-------------------------|-----|-------------------------|-----|
| Other Windows | 2/3 | Masonry | n/a |
| Doors and Surroundings | 4 | Stucco / Render-Plaster | n/a |
| Boundary Walls or Gates | n/a | Outbuildings | n/a |

Historical Context:

The stables in the U plan are present on the 1:2500 OS map of 1897 (but not on the 1880). The eastern range with the coach house do not appear until the 1910 OS (1:2500).

An interesting group which appear to relate to a series of houses rather than one single house.

These buildings are of special local interest as increasingly rare building types of relatively simple construction and detailing. Their local vernacular interest is high and they have evidential and historical value.

| Ownership Type (please lick the appropriate box below). | | | | | |
|---|---|-----------------|--|--|--|
| Private | + | Local Authority | | | |

| Religious / Charity | Stat Undertakers |
|---------------------|------------------|
| | |

Company

Ownership Type (please tick the appropriate box below):

Photographs

Date Taken: 24/01/2011

Any Further Comments:

These buildings generally appear underused and in a poor condition and are vulnerable to further deterioration and loss of historic fabric.

| Surveyor: | JW | Date: | 24/01/2011 |
|-----------|----|-------|------------|

| DUOTOCDADUIC | Client | RUSHMOOR BOROUGH COUNCIL | Title | LOCAL LIST PHOTOGRAPHIC LOG |
|--------------|--------|-----------------------------|--------|--------------------------------|
| PHOTOGRAPHIC | | | | MAHA |
| LOG - LL5016 | Date | 24/01/2010 | Signed | |



Cavendish Mews, former stables and outbuildings, Aldershot – general view



Cavendish Mews, former stables and outbuildings, Aldershot – general view

| PHOTOGRAPHIC | Client | RUSHMOOR BOROUGH COUNCIL | Title | LOCAL LIST PHOTOGRAPHIC LOG |
|--------------|--------|-----------------------------|--------|--------------------------------|
| LOG - LL5016 | Date | 24/01/2010 | Signed | ALLA: |



Cavendish Mews, former stables and outbuildings, Aldershot – view through to eastern range



Cavendish Mews, former stables and outbuildings, Aldershot – eastern range

| DUOTOCRADUIC | Client | RUSHMOOR BOROUGH COUNCIL | Title | LOCAL LIST PHOTOGRAPHIC LOG |
|------------------------------|--------|-----------------------------|--------|--------------------------------|
| PHOTOGRAPHIC LOG - LL5016 | Date | 24/01/2010 | Signed | ALA |
| LOG LLSOIO | | | | |



Cavendish Mews, former stables and outbuildings, Aldershot – eastern range