| Building Name:   Building Reference Number:  | Heritage Asset Survey                 |                             |      |                            |           |     |
|--|---------------------------------------|-----------------------------|------|----------------------------|-----------|-----|
| Building Address:  3 Farnborough Road Aldershot Hampshire GU11 2EX  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed:  Conservation Area:  Date Locally Listed:  Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  (1) Very Bad  2) Poor  3) Fair  4) Good  5) Excellent  Roof  3 Walls  4  Weather Penetration  4 Stability  4  Sag  4 Local Building Cracking  4  Weathering Detail (Valleys etc.)  3 Spalling  4  Rain Water Goods  4 Settlement  4 Settlement  4   | Building Name:                        |                             |      | Building Reference Number: |           |     |
| 3 Famborough Road Aldershot Hampshire GU11 2EX  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: No: + Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Plumb 4  Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Rain Water Goods 4 Settlement 4 Settlement 4   |                                       |                             |      | LL5038                     |           |     |
| Aldershot Hampshire GU11 2EX  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012  |                                       |                             |      | Listing Grade:             |           |     |
| Hampshire GU11 2EX  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: No: +  Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  1 Very Bad  2 Poor  3 Fair  4 Good  5 Excellent  Roof  4 Plumb  4 Stability  4 Covering  3 Pointing  4 Local Building Cracking  4 Plumb  5ag  4 Local Building Cracking  4 Plumb  5ag  Covering  3 Pointing  4 Abutments  3 Roofspread  4 Plumb  4 Stability  4 Flashing  3 EV. Rising Damp  4 Rain Water Goods  4 Settlement  4 Settlement |                                       |                             |      |                            |           |     |
| Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: No: +  Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Stability 4  Weather Penetration 4 Stability 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Rain Water Goods 4 Settlement 4 Settlement  | Aldershot                             |                             |      | I II                       |           |     |
| Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: No: +  Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Stability 4  Weather Penetration 4 Stability 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Rain Water Goods 4 Settlement 4 Settlement  | Hampshire                             |                             |      |                            |           |     |
| Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: No: +  Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  1 Very Bad  2 Poor  3 Fair  4 Good  5 Excellent  Roof  4 Plumb  4 Stability  4 Covering  3 Pointing  4 Local Building Cracking  4 Weather Penetration Valleys etc.)  3 Spalling  4 Weathering Detail (Valleys etc.)  3 Spalling  4 Rain Water Goods  4 Settlement  4 Settlement   | •                                     |                             |      |                            |           |     |
| (see Box B of the SPD)   Date Locally Listed: 26th March 2012   Conservation Area: Yes: No: + Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.    Condition Survey: 1 - 5   |                                       |                             |      | II* Locally                | / Listed  |     |
| (see Box B of the SPD)   Date Locally Listed: 26th March 2012   Conservation Area: Yes: No: + Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.    Condition Survey: 1 - 5   | Listing Criteria Met                  | B. I. K                     |      |                            | _ '       |     |
| SPD    Date Locally Listed:   26 m March 2012   Conservation Area:   Yes:   No: + Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.    Condition Survey: 1-5   | _                                     | _, .,                       |      |                            |           |     |
| Date Locally Listed:   26th March 2012   Conservation Area:   Yes:   No: + Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.    Condition Survey: 1-5  | •                                     |                             |      |                            |           |     |
| Officers Quarters (part of a building which was much larger) now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Stability 4  Weather Penetration 4 Stability 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4  | ,                                     | 26 <sup>th</sup> March 2012 |      | Conservation Area:         | Yes: No:  | +   |
| now partially vacant. Historically the residence of a Senior Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Stability 4  Spread 4 Plumb 4  Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods  |                                       |                             | a bu | ilding which was           |           | )   |
| Royal Engineer Officer. Southern wing of a much larger residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  1 Very Bad  2 Poor  3 Fair  4 Good  5 Excellent  Roof  4 Stability  4 Spread  4 Plumb  4 Sag  4 Local Building Cracking  4 Covering  3 Pointing  4 Abutments  3 Roofspread  4 Plumb  Abutments  3 Roofspread  4 Flashing  3 EV. Rising Damp  4 Rain Water Goods  |                                       |                             |      |                            | _         |     |
| residence, demolished post 1938. Probably mid 19th century and later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Stability 4  Spread 4 Plumb 4  Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Rain Water Goods 4 Settlement 4   |                                       |                             |      |                            |           | O L |
| later. Double pile two storey house. Painted render with low pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 4 Stability 4  Weather Penetration 4 Stability 4  Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   |                                       |                             |      |                            |           | and |
| pitch natural slate roof with wide brick chimneys set to the ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 3 Walls 4 Weather Penetration 4 Stability 4 Spread 4 Plumb 4 Sag 4 Local Building Cracking 4 Covering 3 Pointing 4 Abutments 3 Roofspread 4 Weathering Detail (Valleys etc.) 3 Spalling 4 Rain Water Goods 4 Settlement 4   |                                       |                             |      |                            |           |     |
| ridges of the southern gables. 3 windows to the main front (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 3 Walls 4 Weather Penetration 4 Stability 4 Spread 4 Plumb 4 Sag 4 Local Building Cracking 4 Covering 3 Pointing 4 Abutments 3 Roofspread 4 Weathering Detail (Valleys etc.) 3 Spalling 4 Flashing 3 EV. Rising Damp 4 Rain Water Goods 4 Settlement   | <del>-</del>                          |                             | _    |                            |           |     |
| (facing east). Timber framed vertical sliding sashes to east elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.         Condition Survey: 1-5         1 Very Bad       2 Poor       3 Fair       4 Good       5 Excellent         Roof       3 Walls       4         Weather Penetration       4 Stability       4         Spread       4 Plumb       4         Sag       4 Local Building Cracking       4         Covering       3 Pointing       4         Abutments       3 Roofspread       4         Weathering Detail (Valleys etc.)       3 Spalling       4         Flashing       3 EV. Rising Damp       4         Rain Water Goods       4 Settlement       4   | =                                     |                             |      |                            |           | C   |
| elevation (6-over-6). Double height lean-to timber-framed glasshouse to south elevation, probably a vinery.  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 3 Walls 4 Weather Penetration 4 Stability 4 Spread 4 Plumb 4 Sag 4 Local Building Cracking 4 Covering 3 Pointing 4 Abutments 3 Roofspread 4 Weathering Detail (Valleys etc.) 3 Spalling 4 Flashing 3 EV. Rising Damp 4 Rain Water Goods 4 Settlement 4   |                                       |                             |      |                            |           | a+  |
| Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof 3 Walls 4 Weather Penetration 4 Stability 4 Spread 4 Plumb 4 Sag 4 Local Building Cracking 4 Covering 3 Pointing 4 Abutments 3 Roofspread 4 Weathering Detail (Valleys etc.) 3 Spalling 4 Rain Water Goods 4 Settlement 4   | · · · · · · · · · · · · · · · · · · · |                             |      | _                          |           | SC  |
| Condition Survey: 1 - 5         1 Very Bad         2 Poor         3 Fair         4 Good         5 Excellent           Roof         3 Walls         4           Weather Penetration         4 Stability         4           Spread         4 Plumb         4           Sag         4 Local Building Cracking         4           Covering         3 Pointing         4           Abutments         3 Roofspread         4           Weathering Detail (Valleys etc.)         3 Spalling         4           Flashing         3 EV. Rising Damp         4           Rain Water Goods         4 Settlement         4  |                                       |                             |      |                            |           |     |
| 1 Very Bad         2 Poor         3 Fair         4 Good         5 Excellent           Roof         3 Walls         4           Weather Penetration         4 Stability         4           Spread         4 Plumb         4           Sag         4 Local Building Cracking         4           Covering         3 Pointing         4           Abutments         3 Roofspread         4           Weathering Detail (Valleys etc.)         3 Spalling         4           Flashing         3 EV. Rising Damp         4           Rain Water Goods         4 Settlement         4  | grassnouse to so                      | outh elevation              | on,  | probably a viner           | У•        |     |
| 1 Very Bad         2 Poor         3 Fair         4 Good         5 Excellent           Roof         3 Walls         4           Weather Penetration         4 Stability         4           Spread         4 Plumb         4           Sag         4 Local Building Cracking         4           Covering         3 Pointing         4           Abutments         3 Roofspread         4           Weathering Detail (Valleys etc.)         3 Spalling         4           Flashing         3 EV. Rising Damp         4           Rain Water Goods         4 Settlement         4  | Condition Cumrous 1 F                 |                             |      |                            |           |     |
| Roof3Walls4Weather Penetration4Stability4Spread4Plumb4Sag4Local Building Cracking4Covering3Pointing4Abutments3Roofspread4Weathering Detail (Valleys etc.)3Spalling4Flashing3EV. Rising Damp4Rain Water Goods4Settlement4   | Condition Survey. 1 - 5               |                             |      |                            |           |     |
| Weather Penetration4Stability4Spread4Plumb4Sag4Local Building Cracking4Covering3Pointing4Abutments3Roofspread4Weathering Detail (Valleys etc.)3Spalling4Flashing3EV. Rising Damp4Rain Water Goods4Settlement4  | 1 Very Bad 2                          | 2 Poor (3)                  | Fair | (4) Good (5)               | Excellent |     |
| Weather Penetration4Stability4Spread4Plumb4Sag4Local Building Cracking4Covering3Pointing4Abutments3Roofspread4Weathering Detail (Valleys etc.)3Spalling4Flashing3EV. Rising Damp4Rain Water Goods4Settlement4  | Poof                                  |                             | 2    | Malla                      |           | 14  |
| Spread 4 Plumb 4  Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | KUUI                                  |                             | 3    | vvalis                     |           | 4   |
| Spread 4 Plumb 4  Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | Weather Popetration                   |                             | 1    | Stability                  |           | 1   |
| Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | Weather Felletration                  |                             | 4    | Stability                  |           |     |
| Sag 4 Local Building Cracking 4  Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | Carood                                |                             | 4    | Plumb                      |           |     |
| Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4  | Spread 4                              |                             | 4    | Plumb                      |           | 4   |
| Covering 3 Pointing 4  Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4  | 0-7                                   |                             | 4    | Local Building Crackin     | ~         | 1   |
| Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | Sag 4                                 |                             | 4    | Local Building Cracking    |           | 4   |
| Abutments 3 Roofspread 4  Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | Occupation                            |                             |      | Detection                  |           | 1   |
| Weathering Detail (Valleys etc.) 3 Spalling 4  Flashing 3 EV. Rising Damp 4  Rain Water Goods 4 Settlement 4   | Covering                              |                             | 3    | Pointing                   |           | 4   |
| Weathering Detail (Valleys etc.)  3 Spalling  4 Flashing  3 EV. Rising Damp  4 Rain Water Goods  4 Settlement  4   | Aboutes and                           |                             |      | <b>D</b> (                 |           |     |
| Flashing 3 EV. Rising Damp 4 Rain Water Goods 4 Settlement 4   | Abutments                             |                             | 3    | Roofspread                 |           | 4   |
| Flashing 3 EV. Rising Damp 4 Rain Water Goods 4 Settlement 4   |                                       |                             |      |                            |           |     |
| Rain Water Goods 4 Settlement 4  | Weathering Detail (Vall               | leys etc.)                  | 3    | Spalling                   |           | 4   |
| Rain Water Goods 4 Settlement 4  |                                       |                             |      |                            |           | 1   |
|  | Flashing 3                            |                             | 3    | EV. Rising Damp            |           | 4   |
|  |                                       |                             |      |                            |           |     |
| Chimneys 4 Lintels 4   | Rain Water Goods                      |                             | 4    | Settlement                 |           | 4   |
| Chimneys 4 Lintels 4   |                                       |                             |      |                            |           |     |
|  | Chimneys                              |                             | 4    | Lintels                    |           | 4   |

| Other Features          | 4   | Timber Frame            | n/a |
|-------------------------|-----|-------------------------|-----|
| Windows / Doors         | 4   | Nogging                 | n/a |
| Front Principal Windows | 4   | Post Joints             | n/a |
| Other Windows           | 4   | Masonry                 | n/a |
| Doors and Surroundings  | 4   | Stucco / Render-Plaster | 4   |
| Boundary Walls or Gates | n/a | Outbuildings            | n/a |

## Historical Context:

The 1855 OS map shows a small square plan building on the site of the present Vine cottage. This may well be the present building on the site which is shown, much enlarged on the 1910 OS map. Up until 1938 (OS map extract) an much larger house is shown extending to the north with projecting bays to what appears to be the main part of the house still called 'Vine Cottage'. What remains on site appears to be the southern wing of this much larger house now demolished.

Vinery extensions to houses are very rare especially in a military context and this gives this prominent and notable local building considerable significance.

| Ownership Type (please tick the appropriate box below): |                  |   |  |  |  |
|---|------------------|---|--|--|--|
| Private   | Local Authority  |   |  |  |  |
| Religious / Charity                                     | Stat Undertakers |   |  |  |  |
| Company   | Crown            | + |  |  |  |

## Photographs

Date Taken: 24/09/2010

## Any Further Comments:

Needs to be regularly monitored as although the building is in reasonable repair it appears partially unoccupied.

| Surveyor:   JW   Date:   24/09/2010 |  |
|-------------------------------------|--|
|-------------------------------------|--|

|              | Client | RUSHMOOR BOROUGH<br>COUNCIL | Title  | LOCAL LIST<br>PHOTOGRAPHIC LOG |
|--------------|--------|-----------------------------|--------|--------------------------------|
| PHOTOGRAPHIC |        |                             |        | ARALA                          |
| LOG - LL5038 | Date   | 24/09/2010                  | Signed | MLATO:                         |



Vine Cottage, 3 Farnborough Road, Aldershot - north elevation



Vine Cottage, 3 Farnborough Road, Aldershot - east elevation

|              | Client | RUSHMOOR BOROUGH<br>COUNCIL | Title  | LOCAL LIST<br>PHOTOGRAPHIC LOG |
|--------------|--------|-----------------------------|--------|--------------------------------|
| PHOTOGRAPHIC |        |                             |        | SM112                          |
| LOG - LL5038 | Date   | 24/09/2010                  | Signed | MIAAV:                         |



Vine Cottage, 3 Farnborough Road, Aldershot - south elevation and vinery

|              | Client | RUSHMOOR BOROUGH<br>COUNCIL | Title  | LOCAL LIST<br>PHOTOGRAPHIC LOG |
|--------------|--------|-----------------------------|--------|--------------------------------|
| PHOTOGRAPHIC |        |                             |        | ARALA                          |
| LOG - LL5038 | Date   | 24/09/2010                  | Signed | MIATO:                         |



Vine Cottage, 3 Farnborough Road, Aldershot - south elevation (detail of vinery)