

Heritage Asset Survey

Heritage Asset Survey									
Building Name:	Building Reference Number:								
Natwest Bank	LL5097								
Building Address:	Listing Grade:								
2 Alexandra Road Farnborough Hampshire GU14 6BZ	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 30px; height: 30px;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 30px; height: 30px;" type="checkbox" value="+"/>
I	<input type="checkbox"/>	II	<input type="checkbox"/>						
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 30px; height: 30px;" type="checkbox" value="+"/>						
Listing Criteria Met (see Box B of the SPD)	B, F, H, J								
Date Locally Listed:	26 th March 2012								
Conservation Area:	Yes: + No:								
<p>Bank. 1898-9. 2-storey plus attic with chamfered corner. Flat roofed extension on N side of no special local interest. Square plan of red brick and ashlar with clay tile roof. Ground floor ashlar plinth and red brick risers in Flemish bond. Stone mullion and transoms to windows and ashlar doorcases. Main E doorway with rusticated ashlar doorcase and fluted ionic pilasters with entablature and segmental pediment with shield, scrollwork and foliate design to tympanum. Date stone above reads 1899. Shaped gables, one with dormer, the other a chamfered red brick and ashlar chimney stack. An important corner building which retains much of its original fabric.</p>									
<p>Condition Survey: 1 - 5</p> <table style="width: 100%; border: none;"> <tr> <td style="text-align: center;">1 Very Bad</td> <td style="text-align: center;">2 Poor</td> <td style="text-align: center;">3 Fair</td> <td style="text-align: center;">4 Good</td> <td style="text-align: center;">5 Excellent</td> </tr> </table>		1 Very Bad	2 Poor	3 Fair	4 Good	5 Excellent			
1 Very Bad	2 Poor	3 Fair	4 Good	5 Excellent					
Roof	4	Walls	4						
Weather Penetration	4	Stability	5						
Spread	4	Plumb	5						
Sag	4	Local Building Cracking	4						
Covering	4	Pointing	4						
Abutments	4	Roofspread	4						
Weathering Detail (Valleys etc.)	4	Spalling	4						
Flashing	4	EV. Rising Damp	4						
Rain Water Goods	4	Settlement	5						

Chimneys	4	Lintels	4
Other Features	n/a	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	4
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a
<p>Historical context:</p> <p>Built as London and County Bank in 1898-9</p>			
<p>Ownership Type (please tick the appropriate box below):</p>			
Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input checked="" type="checkbox"/>	Crown	<input type="checkbox"/>
<p>Photographs</p>			
<p>Date Taken: 03/08/10</p>			
<p>Any Further Comments:</p>			
Surveyor:	SH	Date:	04/08/10