

Heritage Asset Survey

Building Name:		Building Reference Number:	
Cemetery Railings And Gates		LL5140	
Building Address:		Listing Grade:	
Ship Lane Farnborough Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD)		C, F, H	
		II* <input type="checkbox"/>	Locally Listed <input type="checkbox"/>
Date Locally Listed:	26 th March 2012	Conservation Area:	Yes: <input type="checkbox"/> No: <input type="checkbox"/>
<p>Gates, screens and railings. c1930. Painted cast and wrought iron. Decorative iron gates and piers to cemetery, diamond gate piers, gates to side alley and railings.</p> <p>Part of the Ship Lane Cemetery group comprising chapel, cemetery lodge, toilet block and gates.</p>			
<p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad <input type="radio"/> 2 Poor <input type="radio"/> 3 Fair <input type="radio"/> 4 Good <input type="radio"/> 5 Excellent </p>			
Roof	n/a	Walls	n/a
Weather Penetration	n/a	Stability	n/a
Spread	n/a	Plumb	n/a
Sag	n/a	Local Building Cracking	n/a
Covering	n/a	Pointing	n/a
Abutments	n/a	Roofspread	n/a
Weathering Detail (Valleys etc.)	n/a	Spalling	n/a
Flashing	n/a	EV. Rising Damp	n/a
Rain Water Goods	n/a	Settlement	n/a
Chimneys	n/a	Lintels	n/a
Other Features	2	Timber Frame	n/a
Windows / Doors	n/a	Nogging	n/a

Front Principal Windows	n/a	Post Joints	n/a
Other Windows	n/a	Masonry	n/a
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	2	Outbuildings	n/a
<p>Historical Context:</p> <p>Forms group with cemetery lodge, chapel and toilet block</p> <p>This building is included on the List of Buildings of Local Significance due to its high historic and aesthetic values.</p>			
Ownership Type (please tick the appropriate box below):			
Private		Local Authority	+
Religious / Charity		Stat Undertakers	
Company		Crown	
Photographs			
Date Taken: 03/08/10			
<p>Any Further Comments:</p> <p>Side gate to alleyway lent up against fence, gate pier has subsided. Significant corrosion of metalwork in places especially to top rail of fencing that has blown apart with expansion; paint has been applied on top.</p>			
Surveyor:	SH	Date:	04/08/10