Heritage Asset Survey						
Building Name:		Building Reference Number:				
Nat West Bank		LL5197				
Building Address:		Listing Grade:				
30 Wellington Street Aldershot GU11 1EA						
		II* Locally Listed +	]			
Date Listed: 22 December 2020		Conservation Area: Yes: No:	+			
Condition Survey: 1 - 5         1       Very Bad       2       Poor       3       Fair       4       Good       5       Excellent						
	Fall					
Feature	Faii	Issue identification				
Feature       Boundary Walls or Gates	n/a	Issue identification Local Building Cracking	n/a			
Feature Boundary Walls or Gates Outbuildings	n/a n/a	Issue identification Local Building Cracking Rising Damp	n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments	n/a n/a n/a	Issue identification Local Building Cracking Rising Damp Roof spread	n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof	n/a n/a n/a 3	Issue identification Local Building Cracking Rising Damp Roof spread Sag	n/a n/a n/a			
Feature Boundary Walls or Gates Outbuildings Abutments Roof Chimneys	n/a n/a n/a 3 3	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement	n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing	n/a n/a n/a 3 3 3	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb	n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)	n/a n/a n/a 3 3 3 3 3	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb Spalling	n/a n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)         Walls (masonry/brickwork/render)	n/a n/a 3 3 3 3 4	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb	n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)         Walls (masonry/brickwork/render)         Pointing	n/a n/a n/a 3 3 3 3 4 4 4	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb Spalling	n/a n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)         Walls (masonry/brickwork/render)         Pointing         Rainwater Goods	n/a n/a 3 3 3 3 4 4 4 3	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb Spalling	n/a n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)         Walls (masonry/brickwork/render)         Pointing         Rainwater Goods         Windows	n/a n/a 3 3 3 3 4 4 4 3 4	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb Spalling	n/a n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)         Walls (masonry/brickwork/render)         Pointing         Rainwater Goods         Windows         Doors and Surroundings	n/a n/a 3 3 3 3 4 4 4 3 4 4 4 4	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb Spalling	n/a n/a n/a n/a n/a n/a			
Feature         Boundary Walls or Gates         Outbuildings         Abutments         Roof         Chimneys         Flashing         Weathering Detail (Valleys etc.)         Walls (masonry/brickwork/render)         Pointing         Rainwater Goods         Windows	n/a n/a 3 3 3 3 4 4 4 3 4	Issue identification Local Building Cracking Rising Damp Roof spread Sag Settlement Stability/ Plumb Spalling	n/a n/a n/a n/a n/a n/a			

Historical Context:

The building was built in 1896 as a bank for the London and County. It was designed by architect William Campbell Jones and is a good example of Victorian architecture. The London and County bank merged with the London and Westminster bank in 1909 and then with the National Provincial bank in 1968; creating the National Westminster bank. The building is situated on the corner of Wellington Street and Victoria Street; a prominent position.

Criteria submitted:

B. The building or structure dates from between 1840 and 1914 and has a definite quality and character

G. The building or structure is an example of identifiable building traditions, techniques and materials that are part of the local architectural style.

H. The building or structure has landmark and/or group value that contributes to the image of the local area.

J. The building is an historic building which has strong architectural interest and is

affected by minor reversible alterations only. If the test of te					
Private		Local Authority			
Religious / Charity		Stat Undertakers			
Company	+	Crown			
Photographs					

