

Heritage Asset Survey

Building Name:		Building Reference Number:		
Boundary Wall To No. 33-39		LL5010		
Building Address:		Listing Grade:		
Brighton Road Aldershot Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>	
Listing Criteria Met (see Box B of the SPD)	B, G, H	II* <input type="checkbox"/>	Locally Listed	<input type="checkbox"/> +
Date Locally Listed:	26 th March 2012	Conservation Area:	Yes:	No: +
Boundary wall. Red and vitrified bricks in Rat-trap bond to Nos. 33-39 Brighton Road. Late 19 th century. 15 courses at highest point with red brick half round coping. Square piers to gate.				
<p>Condition Survey: 1 - 5</p> <p> <input type="radio"/> 1 Very Bad <input type="radio"/> 2 Poor <input type="radio"/> 3 Fair <input type="radio"/> 4 Good <input type="radio"/> 5 Excellent </p>				
Roof	n/a	Walls		3
Weather Penetration	n/a	Stability		4
Spread	n/a	Plumb		3
Sag	n/a	Local Building Cracking		2/3
Covering	n/a	Pointing		2
Abutments	n/a	Roofspread		n/a
Weathering Detail (Valleys etc.)	n/a	Spalling		3
Flashing	n/a	EV. Rising Damp		n/a
Rain Water Goods	n/a	Settlement		n/a
Chimneys	n/a	Lintels		n/a
Other Features	n/a	Timber Frame		n/a
Windows / Doors	n/a	Nogging		n/a

Front Principal Windows	n/a	Post Joints	n/a
Other Windows	n/a	Masonry	n/a
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	3	Outbuildings	n/a
<p>Historical Context:</p> <p>An unusual and increasingly rare use of Rat –trap bond for boundary walls, seen to this part of Hampshire and down to the coast. Whilst the wall has been altered and extended in places it is still a good surviving section of this traditional building type.</p> <p>This building is included on the List of Buildings of Local Significance due to its high evidential and historic values and relatively rarity.</p>			
Ownership Type (please tick the appropriate box below):			
Private	<input checked="" type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>
Photographs			
Date Taken: 04/08/10			
<p>Poor cement pointing has caused spalling in places especially in NW corner. Localised cracking of mortar and one or two bricks</p>			
Surveyor:	SH	Date:	04/08/10

PHOTOGRAPHIC LOG - LL5010	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	04/08/10	Signed	<i>SBHale</i>



Boundary wall to Nos.33-39 (N side)
Brighton Road, Aldershot



Boundary wall to Nos.33-39 (W side)
Brighton Road, Aldershot

PHOTOGRAPHIC LOG - LL5010	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	04/08/10	Signed	<i>SBHale</i>



Boundary wall to Nos.33-39 (W side)

Brighton Road, Aldershot