Heritage Asset Survey								
Building Name:			Building Reference Number:					
Westend Villas			LL5022					
Building Address:			Listing Grade:					
73 - 75 Cranmore Lane								
Aldershot								
Hampshire								
Listing Criteria Met	B, G, H, K		II* Locally Listed +					
(see Box B of the								
SPD)								
Date Locally Listed:	26 th March 2012		Conservation Area: Yes: No: +					
			Red brick with clay tile roo	٦f				
			the road, 2-storey. Red br					
	-							
-		-	gables and clay tile roof.	Ŧ				
-			been pebbledash rendered).					
Offset brick o	jabled entrar	nce	porch with glazed and panel	led				
door with fanl	ight above f	Elan	nked in each house by canted	d				
4-light caseme	ent bay windo	ow w	with tiled roof and 3-light					
casement with	rubbed brick	k he	ead and dripmould. Two pairs	5				
of 2 light cas	sement window	vs w	with glazing bars at first					
2			rubbed brick heads and					
		-	ry wall of red brick with ga	$a \pm a$				
-				ale				
-		o re	etains an iron gate and its					
original raili	ngs.							
Houses and fro	ont boundary	wal	lls and railings form a grou	. qı				
Condition Survey: 1 -	5							
	\sim		\sim					
(1) Very Bad	2) Poor (3)	Fair	(4) Good (5) Excellent					
Roof		3	Walls	5				
		5						
Weather Penetration			Stability	5				
in out of the added		4		5				
Spread		5	Plumb	5				
Opredu		5		5				
Sag		5	Local Building Cracking	4				
Jay		5		4				
Covering			Pointing	4				
Covering		4		4				
Abutmonts			Poofsproad	5				
Abutments		n/a	Roofspread	5				
Mosthering Detail () (all averages)		4	Spalling	1				
Weathering Detail (Valleys etc.)		4	Spalling 4					

Flashing		EV. Rising Damp	4
Rain Water Goods		Settlement	5
Chimneys		Lintels	4
Other Features		Timber Frame	n/a
Windows / Doors		Nogging	n/a
Front Principal Windows		Post Joints	n/a
Other Windows		Masonry	n/a
Doors and Surroundings		Stucco / Render-Plaster	
Boundary Walls or Gates		Outbuildings	

Historical Context:

c.1870, they appear and are named as Cranmore Cottages on the OS 1873 (1:2500) map.

These buildings are included on the List of Buildings of Local Significance due to their high evidential, historic and aesthetic values.

Ownership Type (please tick the appropriate box below):

Private	+	Local Authority				
Religious / Charity		Stat Undertakers				
Company		Crown				
Photographs						
Date Taken: 04/08/10						
Any Further Comments: Moss growth on roof, occasional slipped roof tiles						
Surveyor: SH	D	ate: 04/08/10				



