

## Heritage Asset Survey

Building Name:		Building Reference Number:	
Gates To Former Royal Pavilion		LL5029	
Building Address:		Listing Grade:	
Farnborough Road Aldershot Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD)	B, H, I	II* <input type="checkbox"/>	Locally Listed <input type="checkbox"/> +
Date Locally Listed:	26 <sup>th</sup> March 2012	Conservation Area:	Yes: <input type="checkbox"/> No: +
<p>Gates, gate piers and screens. c1855 Cast iron. Double gates with cross bracing and Y finials and scrolls. Flanking pedestrian gates and railings in matching design but without cross bracing. Gate piers have moulded cappings. Screens have low brick plinth with stone capping.</p> <p>The gates, gate piers and screen railings form a group with the Grade II listed Guardhouse to the former Royal Pavilion.</p> <p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad                <input type="radio"/> 2 Poor                <input type="radio"/> 3 Fair                <input type="radio"/> 4 Good                <input type="radio"/> 5 Excellent         </p>			
Roof	n/a	Walls	2/3
Weather Penetration	n/a	Stability	2/3
Spread	n/a	Plumb	2/3
Sag	n/a	Local Building Cracking	2/3
Covering	n/a	Pointing	2/3
Abutments	n/a	Roofspread	n/a
Weathering Detail (Valleys etc.)	n/a	Spalling	2/3
Flashing	n/a	EV. Rising Damp	2/3
Rain Water Goods	n/a	Settlement	n/a
Chimneys	n/a	Lintels	n/a
Other Features	2/3	Timber Frame	n/a

Windows / Doors	n/a	Nogging	n/a
Front Principal Windows	n/a	Post Joints	n/a
Other Windows	n/a	Masonry	n/a
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	2/3	Outbuildings	n/a

Historical Context:

The gates and railings may date to as early as c1855 and served as the main entrance to the Royal Pavilion (now demolished).

These structures are included on the List of Buildings of Local Significance due to their high evidential and historic values.

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input checked="" type="checkbox"/>

Photographs

Date Taken: 24/09/2010

Any Further Comments:

Excessive paint peeling. Localised corrosion and some failure of stonework where railings are caulked into the stone. Cracked stone plinth with missing pointing.

Surveyor:	JW	Date:	24/09/2010
-----------	----	-------	------------