

Heritage Asset Survey

Heritage Asset Survey	
Building Name:	Building Reference Number:
	LL5105
Building Address:	Listing Grade:
11 - 15 Camp Road Farnborough Hampshire	I <input type="checkbox"/> II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD)	B II* <input type="checkbox"/> Locally Listed <input type="checkbox"/> +
Date Locally Listed:	26 th March 2012
Conservation Area:	Yes: No: +
<p>Shops with accommodation above. c1910. Red and brown brick with faience columns between metal framed shopfronts and clay tile roof. 2-storey. Façade; ground floor green faience tiled pilasters with end consoles. Left hand; car sales garage with transom and mullion fanlight and open frontage, central shop late 20th century shopfront but retaining transom and mullion fanlight, Right hand shop with early-mid 20th century shopfront retaining fanlight above. Plain fascias. First floor central canted oriel with vertical sliding sashes with open pediment above with oculus window in tympanum which has a red brick surround. Red brick quoins. Flanking windows, top sash with glazing bars in red brick surrounds with flat rubbed brick arches and raised keystones. Deep eaves with modillions. Plain clay tile roof.</p>	
<p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> 1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent </p>	
Roof	4 Walls 4
Weather Penetration	4 Stability 4
Spread	4 Plumb 4
Sag	4 Local Building Cracking 4
Covering	4 Pointing 4
Abutments	4 Roofsread 4
Weathering Detail (Valleys etc.)	4 Spalling 4

Flashing	4	EV. Rising Damp	4
Rain Water Goods	3	Settlement	4
Chimneys	4	Lintels	4
Other Features	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Building appears on the 1911 OS (1:2500).

This building is included on the List of Buildings of Local Significance due to its historic and aesthetic values.

Ownership Type (please tick the appropriate box below):

Private	<input checked="" type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>

Photographs

Date Taken: 03/08/10

Any Further Comments: Faience on S pilaster damaged by collision of vehicles passing to the side.

Surveyor: SH

Date: 04/08/10