Heritage Asset Survey						
Building Name:			Building Reference Number:			
Germany Block			LL5167			
Building Address:			Listing Grade:			
Thornhill Barracks						
Gallwey Road						
Aldershot						
Hampshire						
GU11 2DF			II* Locally	/ Listed +		
				-		
Listing Criteria Met H, I, J (see Box B of the SPD)						
Date Locally Listed:	26th March 2012		Conservation Area:	Yes: No:	+	
<pre>single storey range to the north. Red brick with hipped natural roof and red clay ridge tiles. Tall double height windows to east and west elevations (now with later replacement windows). Low stepped plinth of engineering bricks (similar to that of Mauritius Block in part and Singapore Block). String course of double-nailhead decorative bricks links cills to windows (also seen to Singapore Block). Flat gauged brick arches to windows and door openings. Carved timber brackets to projecting eaves matching those seen to Singapore Block. Some blocked openings. Germany Block forms part of the wider group which makes up the architecturally and historically significant Thornhill Barracks complex. Condition Survey: 1-5 1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent</pre>						
Roof		3	Walls		2/3	
Weather Penetration		3	Stability		5	
Spread		5	Plumb		5	
Sag		5	Local Building Crackin	g	4	
Covering		2/3	Pointing		3	
Abutments		3	Roofspread		5	

Weathering Detail (Valleys etc.)	3	Spalling	4
Flashing	3	EV. Rising Damp	1/2
Rain Water Goods	2/3	Settlement	5
Chimneys	5	Lintels	5
Other Features	5	Timber Frame	n/a
Windows / Doors	5	Nogging	n/a
Front Principal Windows	5	Post Joints	n/a
Other Windows	5	Masonry	n/a
Doors and Surroundings	5	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Germany Block forms part of the wider group which makes up the architecturally and historically significant Thornhill Barracks complex. Formerly part of the isolation hospital, probably a ward, Germany Block is one of the earliest buildings on the site, probably original to the Isolation Hospital period (the building appears on the 1898 Ordnance Survey Map) and is therefore of high evidential, historical and aesthetic value, despite alterations to the windows.

Ownership Type (please tick the appropriate box below):

Private	Local Authority					
Religious / Charity	Stat Undertakers					
Company	Crown +					
Photographs						
Date Taken: 24.01.2011						
Any Further Comments:						
Roof appears in places to be in a poor condition, there is evidence of the failure of						
rainwater goods (staining to the walls) and evidence of rising damp (staining to						
brickwork)						
Surveyor: Date:						



Germany Block, Thornhill Barracks, Gallwey Road, Aldershot – north and east elevations