

Heritage Asset Survey

Building Name:		Building Reference Number:	
Technical Store OMA003		LL5006	
Building Address:		Listing Grade:	
St Omer Barracks Alisons Road Aldershot Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>
		II* <input type="checkbox"/>	Locally Listed <input type="checkbox"/> +
Listing Criteria Met (see Box B of the SPD)	B, I		
Date Locally Listed:	26 th March 2012	Conservation Area:	Yes: <input type="checkbox"/> No: + <input type="checkbox"/>
<p>Former Slaughterhouse, c1930s. Red brick in stretcher bond with slate roof. Single-storey long rectangular range with 20 windows. Metal casement windows with opening centre lights under red flat gauged brick arches. Plain vertical boarded doors also with flat gauged brick arches.</p> <p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad <input type="radio"/> 2 Poor <input type="radio"/> 3 Fair <input type="radio"/> 4 Good <input type="radio"/> 5 Excellent </p>			
Roof	4	Walls	4
Weather Penetration	4	Stability	4
Spread	4	Plumb	4
Sag	4	Local Building Cracking	3
Covering	4	Pointing	4
Abutments	n/a	Roofspread	4
Weathering Detail (Valleys etc.)	4	Spalling	4
Flashing	4	EV. Rising Damp	3
Rain Water Goods	3	Settlement	3
Chimneys	4	Lintels	3
Other Features	n/a	Timber Frame	n/a
Windows / Doors	3	Nogging	n/a
Front Principal Windows	3	Post Joints	n/a

Other Windows	3	Masonry	n/a
Doors and Surroundings	3	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Does not appear on the OS 1920 map but is in place by 1938.

A plain functional building though to have been a slaughterhouse.

This building is included on the List of Buildings of Local Significance due to its high evidential and historic values.

Ownership Type (please tick the appropriate box below):

Private	<input checked="" type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>

Photographs

Date Taken: 24/09/2010

Any Further Comments:

Localised cracking of brickwork, rot to bargeboards, glazing to windows broken in places

Surveyor: JW	Date: 24/09/2010
--------------	------------------