

Heritage Asset Survey

Heritage Asset Survey											
Building Name:	Building Reference Number:										
Wesley Hall	LL5009										
Building Address:	Listing Grade:										
Barrack Road Aldershot Hampshire GU11 3NP	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 20px; height: 20px;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>		
I	<input type="checkbox"/>	II	<input type="checkbox"/>								
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>								
Listing Criteria Met (see Box B of the SPD)	B, H, K										
Date Locally Listed:	26 th March 2012										
Conservation Area:	Yes: + No:										
<p>Former Wesleyan Hall. c1890. Local sandstone rubble laid to courses with Bath stone dressings and natural slate roof with terracotta ridge tiles. Rectangular plan orientated NW-SE (described as E-W orientation) with a late 20th century extension to the north and SE turret with conical natural slate roof. S elevation is rendered and painted white. Series of windows with shouldered heads below main south window (probably later insertions). Tripartite lancet windows to three late 20th century hipped roof dormers on both north and south sides. Large geometric tracery south window.</p> <p>The former hall and the stone churchyard walls and iron railings form an important local group of significant buildings.</p>											
<p>Condition Survey: 1 - 5</p> <table style="width: 100%; text-align: center; border: none;"> <tr> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">1</td> <td style="margin-right: 20px;">Very Bad</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">2</td> <td style="margin-right: 20px;">Poor</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">3</td> <td style="margin-right: 20px;">Fair</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">4</td> <td style="margin-right: 20px;">Good</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">5</td> <td>Excellent</td> </tr> </table>		1	Very Bad	2	Poor	3	Fair	4	Good	5	Excellent
1	Very Bad	2	Poor	3	Fair	4	Good	5	Excellent		
Roof	5	Walls	5								
Weather Penetration	5	Stability	5								
Spread	5	Plumb	5								
Sag	5	Local Building Cracking	5								
Covering	5	Pointing	4								
Abutments	5	Roofspread	5								

Weathering Detail (Valleys etc.)	5	Spalling	4
Flashing	5	EV. Rising Damp	4
Rain Water Goods	5	Settlement	5
Chimneys	5	Lintels	5
Other Features	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	5	Post Joints	n/a
Other Windows	5	Masonry	4
Doors and Surroundings	5	Stucco / Render-Plaster	5
Boundary Walls or Gates	4	Outbuildings	n/a
<p>Historical Context:</p> <p>This building is not present on the 1888 OS map but is present by the 1897 map.</p> <p>This building is included on the List of Buildings of Local Significance due to its high evidential, historic, aesthetic and community values.</p>			
Ownership Type (please tick the appropriate box below):			
Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>
Photographs			
Date Taken: 04/08/10			
Extensive vegetation growth to lower storey of turret.			
Surveyor:	SH	Date:	04/08/10

PHOTOGRAPHIC LOG - LL5009	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	04/08/10	Signed	<i>SBHale</i>



Wesley Hall (east end)
Barrack Road, Aldershot



Wesley Hall (south side)
Barrack Road, Aldershot

PHOTOGRAPHIC LOG - LL5009	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	04/08/10	Signed	<i>SBHale</i>



Wesley Hall (north side)

Barrack Road, Aldershot