

## Heritage Asset Survey

<b>Building Name:</b>		<b>Building Reference Number:</b>	
Kitchen Garden Wall, Government House		LL5035	
<b>Building Address:</b>		<b>Listing Grade:</b>	
9 Farnborough Road Aldershot Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>
<b>Listing Criteria Met (see Box B of the SPD)</b>	H, I	II* <input type="checkbox"/>	Locally Listed <input type="checkbox"/> +
<b>Date Locally Listed:</b>	26 <sup>th</sup> March 2012	<b>Conservation Area:</b>	Yes: <input type="checkbox"/> No: +
<p>Kitchen Garden Wall. c1883. Red brick in English bond with stone copings. Wall steps up slope with brick piers between lengths of walls. Projecting band of two courses of brickwork just below coping. Entrances have been bricked-up. Lean-to buildings; glasshouses and other outbuildings survive on the inner face of the northern wall.</p> <p>The kitchen garden wall, stables to the east, guardroom to the south-east all form an important group with the Grade II listed Government House Mess to the south.</p> <p><b>Condition Survey: 1 - 5</b></p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad                <input type="radio"/> 2 Poor                <input type="radio"/> 3 Fair                <input type="radio"/> 4 Good                <input type="radio"/> 5 Excellent         </p>			
Roof	n/a	Walls	2
Weather Penetration	n/a	Stability	3
Spread	n/a	Plumb	3
Sag	n/a	Local Building Cracking	3
Covering	n/a	Pointing	3
Abutments	n/a	Roofspread	n/a
Weathering Detail (Valleys etc.)	n/a	Spalling	2
Flashing	n/a	EV. Rising Damp	2
Rain Water Goods	n/a	Settlement	3
Chimneys	n/a	Lintels	n/a
Other Features	n/a	Timber Frame	n/a

Windows / Doors	n/a	Nogging	n/a
Front Principal Windows	n/a	Post Joints	n/a
Other Windows	n/a	Masonry	n/a
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	1/2

**Historical Context:**

The present Government House Mess (Grade II) was constructed in 1883 and it is likely that the stables, kitchen garden wall and guardhouse were built contemporaneously. The buildings appear in plan as seen today on the 1897 Ordnance Survey (1:2500) map.

The entrances were filled post the IRA attack on the Officers Mess to Rhine Barracks in 1972.

The grouping of this structure with the main house, guardhouse and stable range is of high significance especially given the nationally recognised importance of Government House Mess. For these reasons the kitchen garden wall is considered to have high evidential, historic (in terms of association with Government House Mess) and aesthetic value as a good example of its type.

**Ownership Type (please tick the appropriate box below):**

Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input checked="" type="checkbox"/>

**Photographs**

Date Taken: 24/09/2010

**Any Further Comments:**

Vegetation growth, missing pointing, spalling and missing bricks – this building is **AT RISK**

Surveyor: JW	Date: 24/09/2010
--------------	------------------