	Herita	ge A	sset Su	rvey			
Building Name:			Building F	Reference Nu	mber:		
Stable range to north-			LL5037				
Government House M	ess		Listing Grade:				
Building Address:				<u> </u>			
13 Farnborough Roa	ad			П			
Aldershot	44		· []				
Hampshire							
GU11 2HD			*	Locall	y Listed		
			"	Locali	y Liotod	+	
Listing Criteria Met	G, H, I						
(see Box B of the							
SPD)	2011				1.4		
Date Locally Listed:				tion Area:	Yes:	No: +	
Former range of	_			_		_	
c1883. Red brick							nge
with natural sla		_			_		
single-storey pl				_			,
accommodation lo							_
clay paviours fa		_				:i-pan	е
timber casements			_				م ما
replacements and				_	_		
	brick arches. Much alteration has occurred to the southern end of						I
the stables with part having been converted to residential							
accommodation. Late 20 th century garage doors replace original stable							
entrance to east facade. Coach house and tack room to the north are							
_	the best preserved with large double timber doors with original ironmongery, door and loft opening. Decorative brick aprons below						
		_			_		W
windows to coach	nouse match i	tnose	to Gove	ernment Ho	ouse Mess.		
A good example o	f the time do	anita		odor oltor	ations an		
interventions an							
		-	_	-			~
listed Governmen Wall to the west					i Kitchen	Garde	11
wall to the west	and the Guard	anous	e to the	e south.			
Condition Cumany 1	E						
Condition Survey: 1 -	0						
1 Vary Dad	2 Dear	Га:	1	Cood E	Evacles		
(1) Very Bad	2) Poor (3)	Fair	(4)	Good (5	Excellent		
D (0.40					
Roof		2/3	Walls				4
		_					
Weather Penetration		2	Stability				4
Spread		4	Plumb				4
Sag		4	Local Bu	ilding Cracki	ng		4
				J	Č		
Covering		2/3	Pointing				4
35.59		_,0	39				
Abutments		2/3	Roofspre	ead			4
		_,0					

Weathering Detail (Valleys etc.)	2/3	Spalling	4
Flashing	4	EV. Rising Damp	4
Rain Water Goods	2/3	Settlement	4
Chimneys	3	Lintels	4
Other Features	2/3	Timber Frame	n/a
Windows / Doors	2/3	Nogging	n/a
Front Principal Windows	3	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context: The present Government House Mess (Grade II) was constructed in 1883 and it is likely that the stables, kitchen garden wall and guardhouse were built contemporaneously. The buildings appear in plan as seen today on the 1897 Ordnance Survey (1:2500) map. This map shows additional buildings to the west and east making up what would have been a considerable group of stabling and outbuildings.

Despite some particularly unsympathetic and intrusive alterations to these buildings they retain much of their functional character and quality. The paved yard to the east is a particularly good survival. The grouping of these buildings with the main house, kitchen garden wall and guardhouse is of high significance especially given the nationally recognised importance of Government House Mess. For these reasons the stables are considered to have high evidential (in their altered and original states), historic (in terms of association with Government House Mess) and aesthetic value as good examples of their type.

Ownership Type (please tick the appropriate box below):

Private	Local Authority	
Religious / Charity	Stat Undertakers	
Training to the control of the con		
Company	Crown	+
Company		-
		ı

Photographs

Date Taken: 24/09/2010

Any Further Comments:

The north range and the coach house are presently not in use and vulnerable to falling rapidly into disrepair – loose roof slates and excessive vegetation are signs of potential neglect.

Surveyor: JW Date: 24/09/2010
