

Heritage Asset Survey

Building Name:		Building Reference Number:	
Resettlement Training Centre		LL5041	
Building Address:		Listing Grade:	
Gallwey Road Aldershot Hampshire GU11 2DG		I <input type="checkbox"/>	II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD)		II* <input type="checkbox"/>	Locally Listed <input style="border: 1px solid black; padding: 2px; width: 20px; height: 20px; text-align: center; vertical-align: middle;" type="checkbox" value="+"/>
Listing Criteria Met (see Box B of the SPD)	H, I		
Date Locally Listed:	26 th March 2012	Conservation Area:	Yes: + No:
<p>Signalling School, now training facilities. 1895. Red brick in stretcher bond with slate roofs with tall tapering (in stages) chimney stack. Long symmetrical range to Gallwey Road with extensions to rear and projecting bays to roadside; central entrance and two flanking wings all gabled to Gallwey Road. Single-storey. Red brick in stretcher bond. uPVC replacement windows with cambered brick arches. Chimney stack to the east end has been lost. Chamfered Staffordshire blue brick plinth.</p> <p>An important building in the Gallwey Road group and in a largely as built form to the road elevation with the exception of replacement windows and a lost chimney.</p> <p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> 1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent </p>			
Roof	3	Walls	4
Weather Penetration	4	Stability	4
Spread	4	Plumb	4
Sag	4	Local Building Cracking	4
Covering	3	Pointing	3
Abutments	4	Roofspread	4
Weathering Detail (Valleys etc.)	3	Spalling	4
Flashing	3	EV. Rising Damp	3
Rain Water Goods	3	Settlement	4

Chimneys	4	Lintels	4
Other Features	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	5	Post Joints	n/a
Other Windows	5	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Drawings in the NMR for the Army Signalling School are dated 1895 and signed by William Pitt RE. An extension was built in 1908 to provide a canteen; a use still retained to the present day.

This building is an important part of the Gallwey Road group which includes Fitzwygram House to the west and makes a positive contribution to the character and appearance of the conservation area. Architecturally, the building is striking and well considered with a strong symmetrical composition to the roadside, let down only by the loss of a chimney at the east end.

Source: NMR 95/1781

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input checked="" type="checkbox"/>

Photographs

Date Taken: 24/09/2010

Any Further Comments:

Surveyor: JW	Date: 24/09/2010
--------------	------------------

PHOTOGRAPHIC LOG - LL5041	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	24/09/2010	Signed	



Resettlement Training Centre, Gallwey Road, Aldershot – south and west elevations



Resettlement Training Centre, Gallwey Road, Aldershot – south and part east elevations

PHOTOGRAPHIC LOG - LL5041	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	24/09/2010	Signed	



Resettlement Training Centre, Gallwey Road, Aldershot – east elevation



**Resettlement Training Centre, Gallwey Road, Aldershot – photomontage,
streetscene and setting**