

Heritage Asset Survey

Building Name:		Building Reference Number:	
The Mortuary Chapel		LL5042	
Building Address:		Listing Grade:	
The Military Cemetery Gallwey Road Aldershot Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD)		B, I, K	
		II* <input type="checkbox"/>	Locally Listed <input style="width: 20px; height: 20px; text-align: center; vertical-align: middle;" type="checkbox" value="+"/>
Date Locally Listed:	26 th March 2012	Conservation Area:	Yes: + No:
<p>Memorial Chapel. 1879. Red brick in stretcher bond with buff brick stringcourse and eaves detail and steep natural slate roof. Symmetrical plan with open porch to the west end (probably an addition) and small vestry/private chapel rooms flanking east end with red brick gable end stacks to each. East end, triple lancet windows with the central window extended into the gable. Diamond leaded lights. West end porch with decorative wrought iron gates flanked by lancet openings. Ridge bellcote to west end of the main roof with leaded roof.</p> <p>A striking and attractive building in an important setting at the entrance to the military cemetery.</p> <p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> 1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent </p>			
Roof	5	Walls	4
Weather Penetration	5	Stability	5
Spread	5	Plumb	5
Sag	5	Local Building Cracking	4
Covering	5	Pointing	2/3
Abutments	4	Roofspread	5
Weathering Detail (Valleys etc.)	5	Spalling	3-4
Flashing	5	EV. Rising Damp	2
Rain Water Goods	5	Settlement	4
Chimneys	5	Lintels	4

Other Features	3	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principle Windows	4	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Dated to 1879 by the Property Services Agency and Pevsner, this small Memorial Chapel is an important building in an important and understated setting.

This building is included on the List of Buildings of Local Significance due to its high evidential, historic, aesthetic and community values.

Sources;

Project Connaught Ingram Consultants report (April 2002)

Buildings of England Hampshire: Winchester and the north (2010) Bullen, Crook, Hubbuck and Pevsner p116

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input checked="" type="checkbox"/>

Photographs

Date Taken: 24/09/2010

Any Further Comments:

Possible damp problems due to very high surrounding ground levels. Some poor plastic repairs in places and some repointing required.

Surveyor: JW

Date: 24/09/2010