Building Name:   Crane, Ash Lock   LL5045	Heritage Asset Survey							
Crane, Ash Lock Building Address: Government Road Aldershot Hampshire  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012  Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof  n/a Walls  Weather Penetration  n/a Stability  n/a  Spread  n/a Plumb  n/a  Covering  n/a Pointing  n/a Roofspread  n/a Roofspread  n/a Roofspread  n/a Roofspread  n/a EV. Rising Damp  n/a  Rain Water Goods  n/a Lintels  n/a Lintels	Building Name:			Building Reference Number:				
Building Address:  Government Road Aldershot Hampshire  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012  Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad  2 Poor  3 Fair  4 Good  5 Excellent  Roof  n/a Walls  N/a  Weather Penetration  n/a Stability  n/a  Sag  n/a Local Building Cracking  n/a  Abutments  n/a Roofspread  n/a Roofspread  n/a Roofspread  n/a  Weathering Detail (Valleys etc.)  n/a Spalling  n/a  EV. Rising Damp  n/a  Chimneys  n/a Lintels  n/a  Lintels								
Government Road Aldershot Hampshire  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012	•							
Aldershot Hampshire  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26® March 2012 Conservation Area: Yes: + No:  Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof n/a Walls n/a  Weather Penetration n/a Stability n/a  Sag n/a Local Building Cracking n/a  Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a					-			
Hampshire  Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: + No: Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof n/a Walls n/a  Weather Penetration n/a Stability n/a  Spread n/a Plumb n/a  Sag n/a Local Building Cracking n/a  Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a				1	11			
Listing Criteria Met (see Box B of the SPD)  Date Locally Listed: 26m March 2012					] "			
Listing Criteria Wet (see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: + No:  Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	Tiampsinie				7			
(see Box B of the SPD)  Date Locally Listed: 26th March 2012 Conservation Area: Yes: + No:  Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron.  (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	Listing Critoria Mot	11.1/		II*	Locally	, Listad	+	
SPD    Date Locally Listed:   26th March 2012   Conservation Area:   Yes: +   No:   Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5    Very Bad   2 Poor   3 Fair   4 Good   5 Excellent  Roof   n/a   Walls   n/a  Weather Penetration   n/a Stability   n/a  Sag   n/a Local Building Cracking   n/a  Covering   n/a Pointing   n/a  Abutments   n/a Roofspread   n/a  Weathering Detail (Valleys etc.)   n/a Spalling   n/a  Flashing   n/a EV. Rising Damp   n/a  Rain Water Goods   n/a Settlement   n/a  Chimneys   n/a Lintels   n/a	_	П, К		"	Locali	y Listou		
Date Locally Listed:   26th March 2012   Conservation Area:   Yes: +   No:   Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1   Very Bad   2   Poor   3   Fair   4   Good   5   Excellent  Roof     n/a   Walls     n/a    Weather Penetration   n/a   Stability   n/a    Sag     n/a   Local Building Cracking   n/a    Covering   n/a   Roofspread   n/a    Abutments   n/a   Roofspread   n/a    Weathering Detail (Valleys etc.)   n/a   Spalling   n/a    Rain Water Goods   n/a   Settlement   n/a    Chimneys   n/a   Lintels   n/a	•							
Hand crane on Basingstoke Canal. c1850s. Cast and wrought iron. (similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	,					r		
(similar to those produced by the John Stevenson Canal Foundry, Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	· · · · · · · · · · · · · · · · · · ·						1 -	
Preston). Rotating hand crane comprising a series of gears secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1-5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof n/a Walls n/a  Weather Penetration n/a Stability n/a  Spread n/a Plumb n/a  Sag n/a Local Building Cracking n/a  Covering n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Lintels n/a	Hand crane on E	Basingstoke C	anal	. c1850s	. Cast a	and wroug	ght i	ron.
secured to a vertical post set in a base. Cast-iron frame with jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	(similar to tho	se produced	by t	he John	Stevenso	on Canal	Found	dry,
jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	Preston). Rotat	ing hand cra	ne c	omprisin	ıg a seri	es of ge	ears	
jib and stays. Chain with open hook.  A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	secured to a ve	ertical post	set	in a bas	se. Cast	-iron fi	rame v	with
A good survival of a once common feature to the wharfs and locks of the canals of England and Wales.  The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof		<del>-</del>						
The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	2		1					
The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	A good survival	of a once c	$\circ$ mm $\circ$	n featur	e to the	wharfs	and	
The crane and adjacent lock and Ash Lock Cottage (Grade II listed) form a group  Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof						WIIGEES	arra	
Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	TOCKS OF CHC CO	marb or bigr	ana	and ware				
Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof	The arene and a	diagont logk	and	7ah Too	ole Cottoo	to (Crade	, TT	
Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent  Roof N/a Walls N/a Weather Penetration N/a Stability N/a Spread N/a Plumb N/a Sag N/a Local Building Cracking N/a Covering N/a Pointing N/a Abutments N/a Roofspread N/a Weathering Detail (Valleys etc.) N/a Spalling N/a Flashing N/a EV. Rising Damp N/a Rain Water Goods N/a Settlement N/a Chimneys N/a Lintels N/a			anu	. ASII LOC	k Collag	je (Grade	: 11	
1 Very Bad       2 Poor       3 Fair       4 Good       5 Excellent         Roof       n/a       Walls       n/a         Weather Penetration       n/a Stability       n/a         Spread       n/a Plumb       n/a         Sag       n/a Local Building Cracking       n/a         Covering       n/a Pointing       n/a         Abutments       n/a Roofspread       n/a         Weathering Detail (Valleys etc.)       n/a Spalling       n/a         Flashing       n/a EV. Rising Damp       n/a         Rain Water Goods       n/a Settlement       n/a         Chimneys       n/a Lintels       n/a	listed) form a	group						
1 Very Bad       2 Poor       3 Fair       4 Good       5 Excellent         Roof       n/a       Walls       n/a         Weather Penetration       n/a Stability       n/a         Spread       n/a Plumb       n/a         Sag       n/a Local Building Cracking       n/a         Covering       n/a Pointing       n/a         Abutments       n/a Roofspread       n/a         Weathering Detail (Valleys etc.)       n/a Spalling       n/a         Flashing       n/a EV. Rising Damp       n/a         Rain Water Goods       n/a Settlement       n/a         Chimneys       n/a Lintels       n/a	0 1141 0 4	_						
Roofn/aWallsn/aWeather Penetrationn/aStabilityn/aSpreadn/aPlumbn/aSagn/aLocal Building Crackingn/aCoveringn/aPointingn/aAbutmentsn/aRoofspreadn/aWeathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a	Condition Survey: 1 -	5						
Roofn/aWallsn/aWeather Penetrationn/aStabilityn/aSpreadn/aPlumbn/aSagn/aLocal Building Crackingn/aCoveringn/aPointingn/aAbutmentsn/aRoofspreadn/aWeathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a					. (5	\		
Weather Penetrationn/aStabilityn/aSpreadn/aPlumbn/aSagn/aLocal Building Crackingn/aCoveringn/aPointingn/aAbutmentsn/aRoofspreadn/aWeathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a	(1) Very Bad (2) Poor (3) Fair (4) Good (5) Excellent							
Weather Penetrationn/aStabilityn/aSpreadn/aPlumbn/aSagn/aLocal Building Crackingn/aCoveringn/aPointingn/aAbutmentsn/aRoofspreadn/aWeathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a			1 .	<u> </u>				
Spreadn/aPlumbn/aSagn/aLocal Building Crackingn/aCoveringn/aPointingn/aAbutmentsn/aRoofspreadn/aWeathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a	Roof		n/a	Walls				n/a
Spreadn/aPlumbn/aSagn/aLocal Building Crackingn/aCoveringn/aPointingn/aAbutmentsn/aRoofspreadn/aWeathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a								
Sag n/a Local Building Cracking n/a  Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a	Weather Penetration n/		n/a	Stability				n/a
Sag n/a Local Building Cracking n/a  Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a								
Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a	Spread r		n/a	Plumb				n/a
Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a								
Covering n/a Pointing n/a  Abutments n/a Roofspread n/a  Weathering Detail (Valleys etc.) n/a Spalling n/a  Flashing n/a EV. Rising Damp n/a  Rain Water Goods n/a Settlement n/a  Chimneys n/a Lintels n/a	Sag		n/a	Local Build	ding Crackir	na		n/a
Abutments n/a Roofspread n/a Weathering Detail (Valleys etc.) n/a Spalling n/a Flashing n/a EV. Rising Damp n/a Rain Water Goods n/a Settlement n/a Chimneys n/a Lintels n/a			۱., ۵		g •	.9		1 1/ C
Abutments n/a Roofspread n/a Weathering Detail (Valleys etc.) n/a Spalling n/a Flashing n/a EV. Rising Damp n/a Rain Water Goods n/a Settlement n/a Chimneys n/a Lintels n/a	Covering		n/a	Pointing				n/a
Weathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a	Sovering		11/a	1 Onling				II/a
Weathering Detail (Valleys etc.)n/aSpallingn/aFlashingn/aEV. Rising Dampn/aRain Water Goodsn/aSettlementn/aChimneysn/aLintelsn/a	Abutasanta		/-	Doofonroo	. al			/
Flashing n/a EV. Rising Damp n/a Rain Water Goods n/a Settlement n/a Chimneys n/a Lintels n/a	Abulments		n/a	Rooisprea	ıa			n/a
Flashing n/a EV. Rising Damp n/a Rain Water Goods n/a Settlement n/a Chimneys n/a Lintels n/a	NA		,					,
Rain Water Goods n/a Settlement n/a Chimneys n/a Lintels n/a	Weathering Detail (Valleys etc.)			Spalling				n/a
Rain Water Goods n/a Settlement n/a Chimneys n/a Lintels n/a								
Chimneys n/a Lintels n/a	Flashing n/a		n/a	EV. Rising	g Damp			n/a
Chimneys n/a Lintels n/a								
Chimneys n/a Lintels n/a	Rain Water Goods n/a		n/a	Settlemen	t			n/a
	1,1							
	Chimnevs n/a			Lintels				n/a
Other Features 3 Timber Frame n/a			, 🗸					, 🗸
	Other Features		3	Timber Fra	ame			n/a

Windows / Doors	n/a	Nogging	n/a
Front Principal Windows	n/a	Post Joints	n/a
Other Windows	n/a	Masonry	n/a
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

## **Historical Context:**

A rare survival of a once common building type set to the sides of canal wharfage across the country. Similar in design to those seen to the Stroudwater Canal on the Dudbridge Wharf. These date to 1854.

This building is included on the List of Buildings of Local Significance due to its high evidential and historic values.

Ownership Type (please tick the appropriate box below):				
Private	Local Authority	+ (?)		
Religious / Charity	Stat Undertakers			
Company	Crown			

## Photographs

Date Taken: 23/09/2010

## Any Further Comments:

In a reasonable condition but vulnerable to neglect, it is not clear whether it is still in use?

Surveyor: JW	Date:	23/09/2010
--------------	-------	------------

	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
PHOTOGRAPHIC				ARALA
LOG - LL5045	Date	23/09/2010	Signed	MLATO:



Crane at Ash Lock, Government Road, Aldershot