

## Heritage Asset Survey

Building Name:		Building Reference Number:		
Ash Lock		LL5046		
Building Address:		Listing Grade:		
Government Road Aldershot Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>	
Listing Criteria Met (see Box B of the SPD)	A, E, H, K	II* <input type="checkbox"/>	Locally Listed	<input type="checkbox"/> +
Date Locally Listed:	26 <sup>th</sup> March 2012	Conservation Area:	Yes:	No:
<p>Canal Lock. c1790. Brick chamber walls, with stone coping. 2 sets of double wooden gates, all with mechanical gate paddle gearing. Gravelled heelgrip platforms. Modern stone bollards.</p> <p>The lock, adjacent crane Ash Lock Cottage (Grade II listed) form a group</p> <p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad                <input type="radio"/> 2 Poor                <input type="radio"/> 3 Fair                <input type="radio"/> 4 Good                <input type="radio"/> 5 Excellent         </p>				
Roof	n/a	Walls		4
Weather Penetration	n/a	Stability		4
Spread	n/a	Plumb		4
Sag	n/a	Local Building Cracking		4
Covering	n/a	Pointing		2/3
Abutments	n/a	Roofspread		n/a
Weathering Detail (Valleys etc.)	n/a	Spalling		3
Flashing	n/a	EV. Rising Damp		n/a
Rain Water Goods	n/a	Settlement		n/a
Chimneys	n/a	Lintels		n/a
Other Features	n/a	Timber Frame		n/a
Windows / Doors	n/a	Nogging		n/a
Front Principle Windows	n/a	Post Joints		n/a

Other Windows	n/a	Masonry	3
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a
<p>Historical Context:</p> <p>Canal completed on 4 September 1794. Engineer John Smeaton and his assistant William Jessop worked on the canal, along with Benjamin Henry Latrobe</p> <p>The lock, adjacent crane and Ash Lock Cottage (Grade II listed) form a group.</p> <p>This building is included on the List of Buildings of Local Significance due to its high evidential and historic values.</p>			
Ownership Type (please tick the appropriate box below):			
Private	<input type="checkbox"/>	Local Authority	<input checked="" type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>
Photographs			
Date Taken: 23/09/2011			
<p>Any Further Comments:</p> <p>Some vegetation to mortar joints.</p>			
Surveyor:	JW	Date:	23/09/2011