

Heritage Asset Survey

Heritage Asset Survey											
Building Name:	Building Reference Number:										
Aldershot Railway Station	LL5077										
Building Address:	Listing Grade:										
Station Road Aldershot Hampshire GU11 1HT	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 20px; height: 20px;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>		
I	<input type="checkbox"/>	II	<input type="checkbox"/>								
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>								
Listing Criteria Met (see Box B of the SPD)	B, H, K										
Date Locally Listed:	26 th March 2012										
Conservation Area:	Yes: <input type="checkbox"/> No: <input style="width: 20px; height: 20px;" type="checkbox" value="+"/>										
<p>Train Station. 1870. Buff brick with natural slate roof. 2-storey, originally symmetrical plan; 9 windows flanked either side by single storey ranges enclosing station platforms (probably later additions). Central 4-window range flanked by projecting 2 window bays with hipped roofs. Buff brick in English bond. Semi-circular arched window openings with 2-over-2 horned sashes with rubbed brick surrounds. 7 out of 9 first floor windows are boarded-up (at time of survey - Sept 2010). Double-door entrance with fanlight above. Tall brick stacks corbelled to top. Long canopy (a later addition) extends north.</p>											
<p>Condition Survey: 1 - 5</p> <table style="width: 100%; text-align: center; border: none;"> <tr> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">1</td> <td style="margin-right: 20px;">Very Bad</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">2</td> <td style="margin-right: 20px;">Poor</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">3</td> <td style="margin-right: 20px;">Fair</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">4</td> <td style="margin-right: 20px;">Good</td> <td style="border: 1px solid black; border-radius: 50%; width: 20px; height: 20px; display: inline-block; margin-right: 5px;">5</td> <td>Excellent</td> </tr> </table>		1	Very Bad	2	Poor	3	Fair	4	Good	5	Excellent
1	Very Bad	2	Poor	3	Fair	4	Good	5	Excellent		
Roof	4	Walls	4								
Weather Penetration	4	Stability	4								
Spread	4	Plumb	4								
Sag	4	Local Building Cracking	4								
Covering	4	Pointing	4								
Abutments	4	Roofspread	4								
Weathering Detail (Valleys etc.)	4	Spalling	4								
Flashing	4	EV. Rising Damp	4								

Rain Water Goods	4	Settlement	4
Chimneys	4	Lintels	4
Other Features	n/a	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	4	Outbuildings	n/a

Historical Context:

Built for the London and South Western Railway in 1870

A good example of the building type despite some detrimental later alterations such as an extension to the north and a canopy which has partially destroyed the symmetry of the principal non-trackside elevation.

This building is included on the List of Buildings of Local Significance due to its high evidential, historic, aesthetic and community values.

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input checked="" type="checkbox"/>	Crown	<input type="checkbox"/>

Photographs

Date Taken: 04/08/10

Further comments:

Some occasional missing slates to roof.

Surveyor: SH Date: 04/08/10