Heritage Asset Survey							
Building Name:			Building Reference Number:				
			LL5105				
Building Address:			Listing Grade:				
11 - 15 Camp Road							
Farnborough			1   11				
Hampshire							
Listing Criteria Met (see Box B of the SPD)	В		II* L	ocally L	₋isted	+	
Date Locally Listed:	26th March 2012		Conservation Area	a: \	Yes:	No: +	
Shops with accommodation above. c1910. Red and brown brick with faience columns between metal framed shopfronts and clay tile roof. 2-storey. Façade; ground floor green faience tiled pilasters with end consoles. Left hand; car sales garage with transom and mullion fanlight and open frontage, central shop late 20 <sup>th</sup> century shopfront but retaining transom and mullion fanlight, Right hand shop with early-mid 20 <sup>th</sup> century shopfront retaining fanlight above. Plain fascias. First floor central canted oriel with vertical sliding sashes with open pediment above with oculus window in tympanum which has a red brick surround. Red brick quoins. Flanking windows, top sash with glazing bars in red brick surrounds with flat rubbed brick arches and raised keystones. Deep eaves with modillions. Plain clay tile roof.							
Condition Survey: 1 - 5  1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent							
Roof		4	Walls				4
Weather Penetration		4	Stability				4
Spread		4	Plumb				4
Sag		4	Local Building Cra	acking			4
Covering		4	Pointing				4
Abutments		4	Roofspread				4
Weathering Detail (Va	lleys etc.)	4	Spalling				4

	4		
Flashing		EV. Rising Damp	4
Rain Water Goods	3	Settlement	4
Chimneys	4	Lintels	4
Other Features	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	
Boundary Walls or Gates		Outbuildings	n/a

## **Historical Context:**

Building appears on the 1911 OS (1:2500).

This building is included on the List of Buildings of Local Significance due to its historic and aesthetic values.

Ownership Type (please tick the appropriate box below):					
Private	+	Local Authority			
Religious / Charity		Stat Undertakers			
Company		Crown			

## Photographs

Date Taken: 03/08/10

Any Further Comments: Faience on S pilaster damaged by collision of vehicles passing to the side.

Surveyor:	SH	Date:	04/08/10

## PHOTOGRAPHIC LOG - LL5105

Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
Date	03/08/10	Signed	3BHLe



No. 15 (E elevation)

Camp Road, Farnborough



No. 15 (SE corner)
Camp Road, Farnborough

## PHOTOGRAPHIC LOG - LL5105

Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
Date	03/08/10	Signed	3BHale



No. 15 (SW corner)
Camp Road, Farnborough