Heritage Asset Survey							
Building Name:			Building Reference Number:				
The Clockhouse			LL5109				
Building Address:			Listing Grade:				
Clockhouse Road							
Farnborough			1 11				
Hampshire							
GU14 7QY							
			II* Locall	y Listed $\left \begin{array}{cc} + \end{array} \right $			
Listing Criteria Met	B, F, H, G						
(see Box B of the							
SPD)							
Date Locally Listed:	26th March 2012		Conservation Area:	Yes: No: +			
) . R	ed brick and fa	aux timber-			
Commercial premises. c1900. Red brick and faux timber- framing with clay tile roof. 2-storey plus attic corner							
	-		h bond with ti				
_	_		outh elevation				
					_		
_			el with faux t		_		
			g bay with ent		a		
			aux timber-fra				
			h hipped roof				
			octagonal roo				
faces surmount	ted with lead	ded	cupola with or	nate weather			
vane. Timber o	casement wind	dows	. Oculus windo	w to both so	uth		
and east eleva	ations at gro	ound	l floor level.	Prominent			
corner site.							
Condition Survey: 1 -	5						
1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent							
Roof		4	Walls		4		
Weather Penetration		4	Stability		5		
Spread		5	Plumb		5		
·							
Sag		5	Local Building Crackir	ng	4		
Covering		4	Pointing		4		
Abutments		4	Roofspread		5		
Weathering Detail (Va	ılleys etc.)	4	Spalling		4		
Flashing		4	EV. Rising Damp		4		

			1
Rain Water Goods	4	Settlement	5
Chimneys	4	Lintels	4
Other Features	4	Timber Frame	4
Windows / Doors	4	Nogging	4
Front Principal Windows	4	Post Joints	4
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Not present on the 1895 OS (1:10,560) but present on the 1911 OS (1:2,500).

This building is an important local landmark and is included on the List of Buildings of Local Significance due to its historic and high aesthetic and community values.

Ownership Type (please tick the appropriate box below):						
Private		Local Authority				
Religious / Charity		Stat Undertakers				
Company	+	Crown				
Photographs						
Date Taken: 03/08/10						
Any Further Comments:						
Surveyor: SH		Date: 04/08/10				