Heritage Asset Survey							
Building Name:			Building Reference Number:				
Tradesmans Arms			LL5111				
Building Address:			Listing Grade:				
57 Cove Road							
Farnborough			1   II				
Hampshire				L			
GU14 0EX				_			
			II* Lo	cally Listed	+		
Listing Criteria Met	B, H, J, K			L			
(see Box B of the							
SPD)							
Date Locally Listed:	26th March 2012		Conservation Area	: Yes: N	o: +		
Public House.			y origins, ex	ktended 20 <sup>th</sup>			
century. 2-sto			-				
storey side ra			<b>–</b> –	_	2d		
with painted t	_						
brick stacks.	-	•					
					ana		
floor tripart:					1 1 1 1		
doorway with d			iloor timber	vertical si	Liaing		
sashes with margin lights.							
Condition Survey: 1 -	5						
Condition Survey: 1 -	5 2 Poor (3	Fair	(4) Good (	5 Excellent			
1 Very Bad				5 Excellent			
		Fair 4	4 Good (	5 Excellent	4		
1 Very Bad Roof		4	Walls	5 Excellent			
1 Very Bad				5 Excellent	4 5		
1 Very Bad  Roof  Weather Penetration		4 4	Walls Stability	5 Excellent	5		
1 Very Bad Roof		4	Walls	5 Excellent			
1 Very Bad  Roof  Weather Penetration  Spread		4 4	Walls Stability Plumb		5		
1 Very Bad  Roof  Weather Penetration		4 4	Walls Stability		5		
1 Very Bad  Roof  Weather Penetration  Spread  Sag		4 4	Walls Stability Plumb Local Building Cra		5		
1 Very Bad  Roof  Weather Penetration  Spread		4 4	Walls Stability Plumb		5		
1 Very Bad  Roof  Weather Penetration  Spread  Sag		4 4 4	Walls Stability Plumb Local Building Cra		5 5 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag		4 4 4	Walls Stability Plumb Local Building Cra		5 5 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag  Covering		4 4 4 4	Walls Stability Plumb Local Building Cra		5 5 4 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag  Covering	2 Poor 3	4 4 4 4	Walls Stability Plumb Local Building Cra		5 5 4 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag  Covering  Abutments	2 Poor 3	4 4 4 4	Walls Stability Plumb Local Building Cra Pointing Roofspread		5 5 4 4 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag  Covering  Abutments	2 Poor 3	4 4 4 4	Walls Stability Plumb Local Building Cra Pointing Roofspread		5 5 4 4 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag  Covering  Abutments  Weathering Detail (Value)	2 Poor 3	4 4 4 4 4	Walls Stability Plumb Local Building Cra Pointing Roofspread Spalling		5 5 4 4 4		
1 Very Bad  Roof  Weather Penetration  Spread  Sag  Covering  Abutments  Weathering Detail (Value)	2 Poor 3	4 4 4 4 4	Walls Stability Plumb Local Building Cra Pointing Roofspread Spalling		5 5 4 4 4		
Tolerand  Roof  Weather Penetration  Spread  Sag  Covering  Abutments  Weathering Detail (Value)  Flashing	2 Poor 3	4 4 4 4 4 4	Walls Stability Plumb Local Building Cra Pointing Roofspread Spalling EV. Rising Damp		5 5 4 4 4 4		
Tolerand  Roof  Weather Penetration  Spread  Sag  Covering  Abutments  Weathering Detail (Value)  Flashing	2 Poor 3	4 4 4 4 4 4	Walls Stability Plumb Local Building Cra Pointing Roofspread Spalling EV. Rising Damp		5 5 4 4 4 4		

Other Features		Timber Frame	n/a			
Windows / Doors		Nogging	n/a			
Front Principal Windows	4	Post Joints				
Other Windows	4	Masonry				
Doors and Surroundings	4	Stucco / Render-Plaster 4				
Boundary Walls or Gates	n/a	Outbuildings				
Historical Context:						
Originated as a modest mid-19 <sup>th</sup> century house and later became The Tradesman's Arms, possibly as late as the mid 20 <sup>th</sup> century.						
This building is included on the List of Buildings of Local Significance due to its high historic, aesthetic and potential community values.						
Ownership Type (please tick the appropriate box below):						
Private		Local Authority				
Religious / Charity		Stat Undertakers				
Company		Crown				

Date: 04/08/10

Photographs

Surveyor: SH

Date Taken: 02/08/10

Any Further Comments:

## PHOTOGRAPHIC LOG - LL5111

Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
Date	02/08/10	Signed	3BHL



The Tradesmans Arms (N elevation)
Cove Road, Farnborough



The Tradesmans Arms (W elevation)
Cove Road, Farnborough