

## Heritage Asset Survey

Heritage Asset Survey	
Building Name:	Building Reference Number:
Boundary Wall, La Fosse House	LL5112
Building Address:	Listing Grade:
129 Ship Lane Farnborough Hampshire	I <input type="checkbox"/> II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD)	B, G, H II* <input type="checkbox"/> Locally Listed <input type="checkbox"/> +
Date Locally Listed:	26 <sup>th</sup> March 2012
Conservation Area:	Yes: + No:
<p>Former Kitchen Garden Wall for Farnborough Hill Convent now enclosing a building and enclosing the garden space. 19<sup>th</sup> century, date stone 1872. Rectangular enclosure. Red brick in English bond with clay tile capping. Arched doorway with date stone above and pediment. Buttresses and corner piers with pyramidal capping. Historic tin name plaques of fruit trees that were positioned along the walls.</p>	
<p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad                <input type="radio"/> 2 Poor                <input type="radio"/> 3 Fair                <input type="radio"/> 4 Good                <input type="radio"/> 5 Excellent         </p>	
Roof	2/3 Walls 3
Weather Penetration	2/3 Stability 4
Spread	3 Plumb 4
Sag	4 Local Building Cracking 3
Covering	4 Pointing 2
Abutments	4 Roofspread n/a
Weathering Detail (Valleys etc.)	3 Spalling 2
Flashing	n/a EV. Rising Damp n/a
Rain Water Goods	n/a Settlement 4
Chimneys	n/a Lintels 4

Other Features	n/a	Timber Frame	n/a
Windows / Doors	n/a	Nogging	n/a
Front Principal Windows	n/a	Post Joints	n/a
Other Windows	n/a	Masonry	n/a
Doors and Surroundings	n/a	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context:

Shown on 1880s OS map as a Kitchen Garden Wall with fruit trees and glass houses lining the northern wall . Espalier pear trees are planted on the south-facing wall. This was walled kitchen garden to the Grade II Listed Farnborough Hill Convent.

A modern 20<sup>th</sup> century convent building has been constructed within the garden enclosure.

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input checked="" type="checkbox"/>	Crown	<input type="checkbox"/>

Photographs

Date Taken: 03/08/10

Any Further Comments:

Spalling to brickwork, severe in places. General re-pointing needed. Walls remain plumb.

Surveyor: SH

Date: 04/08/10