

Heritage Asset Survey

| | | | | |
|--|---|-----------------------------|------------------------------|---|
| Building Name: | | Building Reference Number: | | |
| The North Camp | | LL5124 | | |
| Building Address: | | Listing Grade: | | |
| 95 Lynchford Road Farnborough Hampshire GU14 6ET | | I <input type="checkbox"/> | II <input type="checkbox"/> | |
| Listing Criteria Met (see Box B of the SPD) | | B, H, I, K | | II* <input type="checkbox"/> |
| | | | | Locally Listed <input type="checkbox"/> |
| Date Locally Listed: | | 26 th March 2012 | Conservation Area: | Yes: <input type="checkbox"/> |
| | | | No: <input type="checkbox"/> | + |
| <p>Public House. Mid to late 19th century. 2-storey, 3 window main range with lower 2-bay extension (former theatre), central bay projects. Rendered with slate roof and brick stacks. Ground floor public house frontage with green glazed tiles to plinth, risers, pilasters and consoles. Inscribed tiles read 'North Camp Hotel'. Front windows interrupted by three entrance doorways with glazed and panel doors. First floor has timber vertical sliding sashes with central glazing bar with architrave and rusticated keystone. Parapet hides hipped slate roof. The former theatre range has rustication, oversize doorway with stucco voisoirs flanked by ionic columns. Fascia above which is a segmental pediment (hidden by banners at time of survey). Parapet hides roof.</p> | | | | |
| Condition Survey: 1 - 5 | | | | |
| 1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent | | | | |
| Roof | 4 | Walls | 4 | |
| Weather Penetration | 4 | Stability | 5 | |
| Spread | 4 | Plumb | 5 | |
| Sag | 4 | Local Building Cracking | 4 | |
| Covering | 4 | Pointing | 4 | |
| Abutments | 4 | Roofspread | 4 | |
| Weathering Detail (Valleys etc.) | 4 | Spalling | 4 | |
| Flashing | 4 | EV. Rising Damp | 4 | |

| | | | |
|-------------------------|-----|-------------------------|-----|
| | | | |
| Rain Water Goods | 4 | Settlement | 5 |
| Chimneys | 4 | Lintels | 4 |
| Other Features | 4 | Timber Frame | n/a |
| Windows / Doors | 4 | Nogging | n/a |
| Front Principal Windows | 4 | Post Joints | n/a |
| Other Windows | 4 | Masonry | n/a |
| Doors and Surroundings | 4 | Stucco / Render-Plaster | 4 |
| Boundary Walls or Gates | n/a | Outbuildings | n/a |

The Barley Mow preceded the North Camp. The left entrance led to the North Camp theatre, now incorporated into the public house.

This building is included on the List of Buildings of Local Significance due to its high evidential, historic, aesthetic and community values.

Ownership Type (please tick the appropriate box below):

| | | | |
|---------------------|-------------------------------------|------------------|--------------------------|
| Private | <input type="checkbox"/> | Local Authority | <input type="checkbox"/> |
| Religious / Charity | <input type="checkbox"/> | Stat Undertakers | <input type="checkbox"/> |
| Company | <input checked="" type="checkbox"/> | Crown | <input type="checkbox"/> |

Photographs

Date Taken: 03/08/10

Any Further Comments:

Surveyor: SH

Date: 04/08/10

| | | | | |
|--------------------------------------|---------------|-----------------------------|---------------|--------------------------------|
| PHOTOGRAPHIC LOG - LL5124 | Client | RUSHMOOR BOROUGH COUNCIL | Title | LOCAL LIST PHOTOGRAPHIC LOG |
| | Date | 03/08/10 | Signed | <i>SBHale</i> |



The North Camp (S elevation)
95 Lynchford Road, Farnborough