| Heritage Asset Survey | | | | | | | | |
|----------------------------------|---------------------------------------|-------|-------------------------------|----------|--|--|--|--|
| Building Name: | | | Building Reference Number: | | | | | |
| Pillbox | | | LL5129 | | | | | |
| Building Address: | | | Listing Grade: | | | | | |
| Cove Green Allotments | | | | | | | | |
| Prospect Road | | | |] | | | | |
| Farnborough | | | |] | | | | |
| Hampshire | | | | | | | | |
| • | | | II* Locally Listed + | | | | | |
| Listing Criteria Met I | | | | J | | | | |
| (see Box B of the | | | | | | | | |
| SPD) | | | | | | | | |
| Date Locally Listed: | 26 th March 2012 | | Conservation Area: Yes: No: - | - | | | | |
| Pillbox (TYPE | FW3/24). Con | nstr | ructed 1940/1941. Red brick | 2 | | | | |
| | · · · · · · · · · · · · · · · · · · · | | ruction. Retains metal | | | | | |
| | | | eadroom. Faces N defending | r | | | | |
| | | | cool store. A good example | | | | | |
| its type. | | ac | doi store. A good example | <u>U</u> | | | | |
| тсэ суре. | | | | | | | | |
| | | | | | | | | |
| Condition Survey 1 | F | | | | | | | |
| Condition Survey: 1 - | | | | | | | | |
| (1) Very Bad | 2) Poor (3) | Fair | (4) Good (5) Excellent | | | | | |
| | | 1 all | | | | | | |
| Roof | | 3 | Walls | 4 | | | | |
| 11001 | | 5 | | - | | | | |
| Weather Penetration | | 3 | Stability | 5 | | | | |
| | | | | 5 | | | | |
| Spread | | 5 | Plumb | 5 | | | | |
| | | | | - | | | | |
| Sag | | 4 | Local Building Cracking | 4 | | | | |
| 5 | | | | | | | | |
| Covering | | 5 | Pointing | 4 | | | | |
| | | | | | | | | |
| Abutments | | n/a | Roofspread | 4 | | | | |
| | | | | | | | | |
| Weathering Detail (Valleys etc.) | | n/a | Spalling | 4 | | | | |
| | | | | | | | | |
| Flashing | | n/a | EV. Rising Damp | 2 | | | | |
| | | | | | | | | |
| Rain Water Goods | | n/a | Settlement | 5 | | | | |
| | | | | | | | | |
| Chimneys | | n/a | Lintels | 4 | | | | |
| | | | | | | | | |
| Other Features | | n/a | Timber Frame | n/a | | | | |
| | | | | | | | | |
| Windows / Doors | | n/a | Nogging | n/a | | | | |
| | | | | | | | | |

| Front Principal Windows | n/a | Post Joints | n/a |
|-------------------------|-----|-------------------------|-----|
| Other Windows | n/a | Masonry | 4 |
| Doors and Surroundings | n/a | Stucco / Render-Plaster | n/a |
| Boundary Walls or Gates | n/a | Outbuildings | n/a |

Historical Context:

Part of the WWII line of defences along the mainline railway.

This building is included on the List of Buildings of Local Significance due to its high evidential and historic values.

Ownership Type (please tick the appropriate box below):

| Private | Local Authority | + | | | | |
|---|------------------|---|--|--|--|--|
| | | | | | | |
| Religious / Charity | Stat Undertakers | | | | | |
| | | | | | | |
| Company | Crown | | | | | |
| | | | | | | |
| Photographs | | | | | | |
| | | | | | | |
| Date Taken: 03/08/10 | | | | | | |
| | | | | | | |
| Any Further Comments: Concrete roof topped with vegetation growth | | | | | | |
| | | | | | | |
| | | | | | | |
| Surveyor: SH | Date: 04/08/10 | | | | | |



Pillbox Prospect Road, Farnborough