

Heritage Asset Survey

Heritage Asset Survey									
Building Name:	Building Reference Number:								
Church Of Our Lady	LL5130								
Building Address:	Listing Grade:								
Queens Road Farnborough Hampshire GU14 6JR	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 20px; height: 20px;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>
I	<input type="checkbox"/>	II	<input type="checkbox"/>						
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>						
Listing Criteria Met (see Box B of the SPD)	B, J, K								
Date Locally Listed:	26 th March 2012								
Conservation Area:	Yes: <input type="checkbox"/> No: <input checked="" type="checkbox"/>								
<p>Catholic Church. c.1901. Red brick, ashlar and natural slate roof. Single-cell ecclesiastical plan with south porch with dormer above (dormer mirrored on the north elevation). Red brick in Flemish bond with ogee tripartite ashlar windows with label stop hoodmoulds with leaded diamond lights with central stained glass cross. Red brick buttresses. Blank east end. Rendered blank west end. Attached via link to new church built as a Jubilee celebration in 2000 by the Sarum Partnership. The 1901 church has been converted into the church hall.</p>									
<p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> 1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent </p>									
Roof	5	Walls	4						
Weather Penetration	5	Stability	5						
Spread	5	Plumb	5						
Sag	5	Local Building Cracking	5						
Covering	4	Pointing	4						
Abutments	4	Roofspread	5						
Weathering Detail (Valleys etc.)	4	Spalling	4						
Flashing	4	EV. Rising Damp	4						

Rain Water Goods	4	Settlement	5
Chimneys	n/a	Lintels	5
Other Features	n/a	Timber Frame	n/a
Windows / Doors	5	Nogging	n/a
Front Principal Windows	5	Post Joints	n/a
Other Windows	5	Masonry	5
Doors and Surroundings	5	Stucco / Render-Plaster	4
Boundary Walls or Gates	n/a	Outbuildings	n/a
Historical Context:			
Ownership Type (please tick the appropriate box below):			
Private		Local Authority	
Religious / Charity	+	Stat Undertakers	
Company		Crown	
Photographs			
Date Taken: 03/08/10			
Any Further Comments: Ivy growth on E end			
Surveyor:	SH	Date:	04/08/10