

## Heritage Asset Survey

Heritage Asset Survey									
Building Name:	Building Reference Number:								
	LL5132								
Building Address:	Listing Grade:								
St Marks Church Of England Primary School Queens Road Farnborough Hampshire GU14 6DU	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 30px; height: 30px;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 30px; height: 30px;" type="checkbox" value="+"/>
I	<input type="checkbox"/>	II	<input type="checkbox"/>						
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 30px; height: 30px;" type="checkbox" value="+"/>						
Listing Criteria Met (see Box B of the SPD)	B								
Date Locally Listed:	26 <sup>th</sup> March 2012								
Conservation Area:	Yes: <input type="checkbox"/> No: <input checked="" type="checkbox"/>								
<p>School. 1897. Plan comprising E and W ranges forming an 'L' and central range. Modern late 20<sup>th</sup> century south range. Red brick, ashlar and clay tile roof. Single-storey gabled ranges. Red brick in Flemish bond. Replacement uPVC windows under red brick arches. Separate entrances with lintels inscribed '<i>Infants, girls, boys</i>'. Tile hanging to some gables with fish-scale bands. Grey brick cross motif in east range north gable. North elevation foundation stone with ashlar niche above with statue of St Mark. Leaded ridge ventilators to roof. Timber and leaded cupola to east range. Cupola to west range with pyramidal clay tiled roof. Tall bellcote to west range in bands of brick and ashlar with weather vane. Iron railings to N side.</p>									
<p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">1</span> Very Bad                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">2</span> Poor                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">3</span> Fair                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">4</span> Good                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">5</span> Excellent         </p>									
Roof	4	Walls	4						
Weather Penetration	5	Stability	5						
Spread	5	Plumb	5						
Sag	5	Local Building Cracking	5						
Covering	4	Pointing	4						
Abutments	4	Roofspread	5						

Weathering Detail (Valleys etc.)	4	Spalling	4
Flashing	4	EV. Rising Damp	4
Rain Water Goods	4	Settlement	5
Chimneys	n/a	Lintels	5
Other Features (cupola)	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	4
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	4	Outbuildings	n/a
<p>Historical Context: Foundation stone laid by Duchess of Connaught &amp; Strathearn, May 19<sup>th</sup> 1897</p> <p>This building is included on the List of Buildings of Local Significance due to its high historic, aesthetic and community values.</p>			
Ownership Type (please tick the appropriate box below):			
Private	<input type="checkbox"/>	Local Authority	<input checked="" type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>
Photographs			
Date Taken: 03/08/10			
Any Further Comments:			
Surveyor:	SH	Date:	04/08/10