

## Heritage Asset Survey

Heritage Asset Survey									
Building Name:	Building Reference Number:								
	LL5135								
Building Address:	Listing Grade:								
North Farnborough County Infant School Rectory Road Farnborough Hampshire GU14 8AJ	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 20px; height: 20px;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>
I	<input type="checkbox"/>	II	<input type="checkbox"/>						
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px;" type="checkbox" value="+"/>						
Listing Criteria Met (see Box B of the SPD)	B, K								
Date Locally Listed:	26 <sup>th</sup> March 2012								
Conservation Area:	Yes: +      No:								
<p>School. Mid 19<sup>th</sup> century with late 19<sup>th</sup> and early 20<sup>th</sup> extensions and alterations. Red brick with brick stacks and clay tile roof. Single-storey, irregular plan of gabled ranges comprising original school building and later extensions and additions. Original complex red brick in English bond with diaper work in vitrified headers. Large casement gable windows with brick or ashlar surrounds, central range (Mid 19<sup>th</sup> century) window ecclesiastical in style. Timber casements or uPVC replacements. Later brick ranges (late 19<sup>th</sup>/early 20<sup>th</sup> century and late 20<sup>th</sup> century), all gabled with varied end window fenestration. School bell in gable of main range. Girls and Boys entrances.</p>									
<p>Condition Survey: 1 - 5</p> <table style="width: 100%; border: none;"> <tr> <td style="text-align: center;"><span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">1</span> Very Bad</td> <td style="text-align: center;"><span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">2</span> Poor</td> <td style="text-align: center;"><span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">3</span> Fair</td> <td style="text-align: center;"><span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">4</span> Good</td> <td style="text-align: center;"><span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">5</span> Excellent</td> </tr> </table>		<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">1</span> Very Bad	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">2</span> Poor	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">3</span> Fair	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">4</span> Good	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">5</span> Excellent			
<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">1</span> Very Bad	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">2</span> Poor	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">3</span> Fair	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">4</span> Good	<span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px;">5</span> Excellent					
Roof	4	Walls	4						
Weather Penetration	4	Stability	5						
Spread	4	Plumb	4						
Sag	4	Local Building Cracking	4						
Covering	4	Pointing	4						
Abutments	4	Roofspread	5						
Weathering Detail (Valleys etc.)	4	Spalling	4						

Flashing	4	EV. Rising Damp	4
Rain Water Goods	4	Settlement	4
Chimneys	4	Lintels	4
Other Features	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	4
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	n/a	Outbuildings	n/a

Historical Context: Appears to be two phases of construction with the diaper work brick to the original build (present as the 'National School – boys and girls' on the OS 1874 (1<sup>st</sup> ed) OS 1:10,560) with later extensions through to the late 20<sup>th</sup> century.

This building is included on the List of Buildings of Local Significance due to its high evidential, historic, aesthetic and community values.

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input checked="" type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>

Photographs

Date Taken: 03/08/10

Any Further Comments:

Surveyor: SH

Date: 04/08/10