

Heritage Asset Survey

Building Name:		Building Reference Number:	
Chapel And Hearse House		LL5144	
Building Address:		Listing Grade:	
Victoria Road Cemetery Victoria Road Farnborough Hampshire		I <input type="checkbox"/>	II <input type="checkbox"/>
Listing Criteria Met (see Box B of the SPD) B, E, H, K		II* <input type="checkbox"/>	Locally Listed <input type="checkbox"/> +
Date Locally Listed:	13 th March 2012	Conservation Area:	Yes: <input type="checkbox"/> No: <input type="checkbox"/> +
<p>Chapel & Hearse House. 1859. By David Smith of Frimley. Red brick, vitrified chequer pattern headers, ashlar and natural slate. Single cell plan with west porch and north vestry. Trefoil headed windows. West porch with inscription '<i>I am the resurrection and the life saith the Lord</i>' with statue in a niche above. Ashlar capped brick buttresses. West bellcote. Gabled roof with ornate ridge tiles. Windows and doors boarded up at time of survey (August 2010).</p> <p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <input type="radio"/> 1 Very Bad <input type="radio"/> 2 Poor <input type="radio"/> 3 Fair <input type="radio"/> 4 Good <input type="radio"/> 5 Excellent </p>			
Roof	1	Walls	3
Weather Penetration	1	Stability	4
Spread	4	Plumb	4
Sag	3	Local Building Cracking	4
Covering	1	Pointing	3
Abutments	4	Roofspread	3
Weathering Detail (Valleys etc.)	2	Spalling	3
Flashing	2	EV. Rising Damp	3
Rain Water Goods	2	Settlement	3
Chimneys	n/a	Lintels	3
Other Features	n/a	Timber Frame	n/a

Windows / Doors	3	Nogging	n/a
Front Principal Windows	2	Post Joints	n/a
Other Windows	2	Masonry	3
Doors and Surroundings	2	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	3	Outbuildings	n/a

Historical Context:

Built as a cemetery chapel in 1859. Built at a cost of £283. Iron railings and gates by Reuben Yates.

Important setting with Victorian cemetery, yew trees, boundary railings and hedges, significant Queen Victoria memorial in cemetery.

This building is included on the List of Buildings of Local Significance due to its high evidential, historic, aesthetic and community values.

Source:(Gosney, *Farnborough Past*)

Ownership Type (please tick the appropriate box below):

Private	<input type="checkbox"/>	Local Authority	<input checked="" type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input type="checkbox"/>	Crown	<input type="checkbox"/>

Photographs

Date Taken: 02/08/10

Any Further Comments:

BAR. Very poor condition with missing slates on roof, dislodged gable capping stones, boarded up windows and doors.

Surveyor: SH

Date: 02/08/10

PHOTOGRAPHIC LOG - LL5144	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	02/08/10	Signed	<i>SBHale</i>



Chapel & hearse house (W elevation)

Victoria Road, Farnborough



Chapel & hearse house (S elevation)

Victoria Road, Farnborough

PHOTOGRAPHIC LOG - LL5144	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
	Date	02/08/10	Signed	<i>SBHale</i>



Chapel & hearse house (N elevation)

Victoria Road, Farnborough



Chapel & hearse house (E elevation)

Victoria Road, Farnborough