

## Heritage Asset Survey

Heritage Asset Survey									
Building Name:	Building Reference Number:								
The Trafalgar	LL5147								
Building Address:	Listing Grade:								
1 Short Street Aldershot Hampshire GU11 1HA	<table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">I</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> <td style="width: 25%;">II</td> <td style="width: 25%; text-align: center;"><input type="checkbox"/></td> </tr> <tr> <td>II*</td> <td style="text-align: center;"><input type="checkbox"/></td> <td>Locally Listed</td> <td style="text-align: center;"><input style="width: 20px; height: 20px; vertical-align: middle;" type="checkbox" value="+"/></td> </tr> </table>	I	<input type="checkbox"/>	II	<input type="checkbox"/>	II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px; vertical-align: middle;" type="checkbox" value="+"/>
I	<input type="checkbox"/>	II	<input type="checkbox"/>						
II*	<input type="checkbox"/>	Locally Listed	<input style="width: 20px; height: 20px; vertical-align: middle;" type="checkbox" value="+"/>						
Listing Criteria Met (see Box B of the SPD)	B, I, J								
Date Locally Listed:	26 <sup>th</sup> March 2012								
Conservation Area:	Yes: <input type="checkbox"/> No: <input checked="" type="checkbox"/>								
<p>Public House. Mid 19<sup>th</sup> century. Red brick in Flemish Garden Wall bond and painted render with natural slate roof. 2-storey building addressing the corner with corner entrance door. Ground floor rendered with timber casements. Narrow fascia with pub name with red brick first floor. First floor windows are 3-over-3 pane vertical sliding sashes with flat gauged brick arches. Slate roof with tall red brick stacks and terracotta pots.</p>									
<p>Condition Survey: 1 - 5</p> <p style="text-align: center;"> <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">1</span> Very Bad                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">2</span> Poor                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">3</span> Fair                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">4</span> Good                <span style="border: 1px solid black; border-radius: 50%; padding: 2px 5px; margin: 0 5px;">5</span> Excellent         </p>									
Roof	4								
Walls	4								
Weather Penetration	4								
Stability	4								
Spread	4								
Plumb	4								
Sag	4								
Local Building Cracking	4								
Covering	4								
Pointing	4								
Abutments	n/a								
Roofspread	4								
Weathering Detail (Valleys etc.)	4								
Spalling	4								
Flashing	4								
EV. Rising Damp	4								
Rain Water Goods	4								
Settlement	4								
Chimneys	4								
Lintels	4								
Other Features	n/a								
Timber Frame	n/a								

Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	4
Boundary Walls or Gates	n/a	Outbuildings	n/a
<p>Historical Context:</p> <p>This building is included on the List of Buildings of Local Significance due to its high historic, aesthetic and community values.</p>			
<p>Ownership Type (please tick the appropriate box below):</p>			
Private	<input type="checkbox"/>	Local Authority	<input type="checkbox"/>
Religious / Charity	<input type="checkbox"/>	Stat Undertakers	<input type="checkbox"/>
Company	<input checked="" type="checkbox"/>	Crown	<input type="checkbox"/>
<p>Photographs</p>			
<p>Date Taken: 04/08/10</p>			
<p>Any Further Comments:</p>			
Surveyor:	SH	Date:	04/08/10