Heritage Asset Survey							
Building Name:			ding Ref	erence N	umber:		
Tumbledown Dick Public House		LL5					
Building Address:		Listing Grade:					
227 Farnborough Road							
Farnborough		I		II			
GU14 7JT							
				Loop	lly Lieted		
Listing criteria met (see box B of the SPD)	A,H,I, K	*		Loca	lly Listed	+	
Date Locally Listed	23 <sup>rd</sup> April 2013	Cor	nservation	n Area:	Yes:	No: +	
The two-storey	building fron	ts c	nto tl	he Far	nborou	gh Road	l .
The large two s	storey Norther	n pa	rt is	five	windows	s wide,	
with a central	——————————————————————————————————————						
		_			_		
open porch. The roof of the building is slate with a hipped roof and there is a two-storey bay window on the							
North West corner. There is a small single storey addition							
on the Northern most part of the building. This has a							
single door and a pitched plain clay tile roof. The							
building is constructed/faced in an orange terracotta							
				_			w .
brick. Flat rendered arches at first floor to each window, with protruding black painted sills. The ground floor							
with protruding black painted sills. The ground floor windows have semi-circular brick window arches, within							
painted render							
storey element				-			
three on the fi				_			
fenestration and							
most section.							
hipped roof rar							a
rendered rear e				_			
to ceiling heigh				_			
storey structure with central doorway giving access to a							
	large open room. The entrance door has a rendered surround						
with a fanlight over. Further South is a single storey							
structure of three windows wide, with a clay tile hipped							
roof. To the rear of the main buildings fronting the road,							
are a number of structures and a tarmac car park.							
Condition Survey: 1 - 5							
1 Very Bad 2 Poor 3 Fair 4 Good 5 Excellent							
Roof	3	Wa	alls				3
Weather Penetration	3	Sta	ability				4

Spread	5	Plumb	4
Sag	4	Local Building Cracking	4
Covering	3	Pointing	4
Abutments	4	Roofspread	4
Weathering Detail (Valleys etc.)	3	Spalling	4
Flashing	3	EV. Rising Damp	4
Rain Water Goods	3	Settlement	5
Chimneys	4 Lintels		5
Other Features	4	Timber Frame	n/a
Windows / Doors	4	Nogging	n/a
Front Principal Windows	4	Post Joints	n/a
Other Windows	4	Masonry	n/a
Doors and Surroundings	4	Stucco / Render-Plaster	n/a
Boundary Walls or Gates	5	Outbuildings	n/a

## **Historical Context:**

The building has had significant changes, both internally and externally. The building is a traditional mid 19<sup>th</sup> Century public house. The sales particulars of 1825 refer to it as 'newly erected. The building has no significant architectural merit to qualify for statutory National listing. The key historical features of the building that remain include the Victorian fenestration surrounds and details, the remaining chimney stacks, both internal and external, the plain Welsh slate roofs, the entrance door, doorway, fanlight and internal window surrounds. The building, its site and name are of local significance and forms part of the wider local heritage. For this reason the building is included on the List of Buildings of Local Importance due to its historic associations and communal value.

associations and communal value.		
Ownership Type (please tick the approp	riate l	oox below):
Private		Local Authority
Religious / Charity		Stat Undertakers
Company	+	Crown
Donort: IT		Note: 01/07/12

DUOTOCRADUIC	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG	
PHOTOGRAPHIC LOG - LL5186				MAAA	
LOG - LL5186	Date	23/04/2013	Signed	V XLAIII SY;	



Tumbledown Dick, 227 Farnborough Road, Farnborough, GU14 7JT



Tumbledown Dick, 227 Farnborough Road, Farnborough, GU14 7JT

DUOTOCDADUIC	Client	RUSHMOOR BOROUGH COUNCIL	Title	LOCAL LIST PHOTOGRAPHIC LOG
PHOTOGRAPHIC				donne
LOG - LL5186	Date	23/04/2013	Signed	MAA:



Tumbledown Dick, 227 Farnborough Road, Farnborough, GU14 7JT



Tumbledown Dick, 227 Farnborough Road, Farnborough, GU14 7JT