

## Heritage Asset Survey

<b>Building Name:</b>		<b>Building Reference Number:</b>	
Imperial Standard Public House		LL5185	
<b>Building Address:</b>		<b>Listing Grade:</b>	
25 Western Road Aldershot GU11 3PL		I <input type="checkbox"/>	II <input type="checkbox"/>
<b>Listing criteria met (see box B of the SPD)</b>	B, H	II* <input type="checkbox"/>	Locally Listed <input style="width: 20px; height: 20px; text-align: center; vertical-align: middle;" type="checkbox" value="+"/>
<b>Date Locally Listed</b>	20/10/15	<b>Conservation Area:</b>	Yes: <input type="checkbox"/> No: <input style="width: 20px; height: 20px; text-align: center; vertical-align: middle;" type="checkbox" value="+"/>
Painted render walls with a slate roof. Arched ground floor windows and entrance door, with plaster moulded arches. Pilasters. Modern Upvc/trickle vent second floor windows. Modern lighting at eaves level, traditional lighting at ground floor.			
<b>Condition Survey: 1 - 5</b> <div style="display: flex; justify-content: space-around; align-items: center;"> <span style="border: 1px solid black; border-radius: 50%; padding: 5px; margin: 0 5px;">1</span> Very Bad                     <span style="border: 1px solid black; border-radius: 50%; padding: 5px; margin: 0 5px;">2</span> Poor                     <span style="border: 1px solid black; border-radius: 50%; padding: 5px; margin: 0 5px;">3</span> Fair                     <span style="border: 1px solid black; border-radius: 50%; padding: 5px; margin: 0 5px;">4</span> Good                     <span style="border: 1px solid black; border-radius: 50%; padding: 5px; margin: 0 5px;">5</span> Excellent                 </div>			
Roof	3	Walls	4
Weather Penetration	4	Stability	4
Spread	n/a	Plumb	n/a
Sag	n/a	Local Building Cracking	n/a
Covering	n/a	Pointing	n/a
Abutments	n/a	Roofspread	n/a
Weathering Detail (Valleys etc.)	n/a	Spalling	n/a
Flashing	3	EV. Rising Damp	n/a
Rain Water Goods	3	Settlement	n/a
Chimneys	4	Lintels	n/a
Other Features	4	Timber Frame	n/a
Windows / Doors ff	2	Nogging	n/a
Front Principal Windows / Doors gf	4	Post Joints	n/a



<b>PHOTOGRAPHIC LOG - LL5185</b>	<b>Client</b>	RUSHMOOR BOROUGH COUNCIL	<b>Title</b>	LOCAL LIST PHOTOGRAPHIC LOG
	<b>Date</b>	20/10/15	<b>Signed</b>	<i>SBHale</i>



**Imperial Standard Public House, 25 Western Road**



**Imperial Standard Public House, 25 Western Road**

<b>PHOTOGRAPHIC LOG - LL5185</b>	<b>Client</b>	RUSHMOOR BOROUGH COUNCIL	<b>Title</b>	LOCAL LIST PHOTOGRAPHIC LOG
	<b>Date</b>	20/10/15	<b>Signed</b>	<i>SBHale</i>



**Imperial Standard Public House, 25 Western Road**



**Imperial Standard Public House, 25 Western Road**